

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22007413/APA3Q2**Date:** 13/03/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002470821
Claimant Vehicle No :	SJS1495E	Insured Vehicle No :	PC7711E
Date of Loss:	03/08/2022	Nature of Claim:	TP
		Claim No:	202222005944

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS1495E	Engine No:	G4FGJH723738
Make & Model:	KIA CERATO, 1.6 EX (A)	Chassis No:	KNAF3416MK5032385
Reg. Date:	09/04/2019 (Man. Year: 2018)	Odometer:	66519 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,664.55	12,183.01	2,481.54	16.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,970.00	3,420.00	1,550.00	31.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,634.55	15,603.01	4,031.54	20.53
Approved Total (Overridden) (S\$)		12,400.00		
Nett Amount (S\$)	19,634.55	12,400.00	7,234.55	36.85

INSPECTION

Date of Assignment:	03/08/2022	Ryder Auto Pte Ltd (HQ)
Date Inspected:	03/08/2022 Inspected At:	2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
Estimated Period of Repair:	12.0 days	Singapore 417921

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2023)
Parts: 143	KIA CERATO 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJS1495E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	880.50 FL	*688.00 FL
2	3		*REAR BUMPER BRACKET MIDDLE (LOWER)	Damaged	180.00 FL	*60.00 FL
3	2		*REAR BUMPER BRACKET MIDDLE (UPPER)	Damaged	80.00 FL	*40.00 FL
4	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	560.00 FL	*280.00 FL
5	1		*REAR BUMPER REVERSE SENSOR WIRE	Not Necessary	102.00 FL	*- FL
6	1		*REAR BUMPER O/S & N/S SIDE UNDER COVER	N/S Torn	224.40 FL	*112.20 FL
7	1		*REAR BUMPER O/S & N/S RETAINER	Damaged	226.40 FL	*226.40 FL
8	1		*REAR BUMPER CENTRE RETAINER	Not Necessary	90.00 FL	*- FL
9	1		*REAR BUMPER N/S & O/S REFLECTOR	Cracked	442.60 FL	*396.00 FL
10	2		*REAR BUMPER N/S & O/S REFLECTOR GARNISH	Deformed	70.00 FL	*70.00 FL
11	1		*REAR BUMPER LOWER DIFFUSER	Distorted	285.30 FL	*285.30 FL
12	2		*REAR O/S & N/S TAIL LAMP	Cracked	897.20 FL	*897.20 FL
13	1		*REAR BOOTLID	Distorted	1,895.80 FL	*1,297.00 FL
14	1		*REAR BOOTLID WEATHERSTRIP	Cut	132.40 FL	*132.40 FL
15	1		*REAR BOOTLID EMBLEM	Necessary	71.20 FL	*71.20 FL
16	1		*REAR BOOTLID CERATO EMBLEM	Necessary	66.00 FL	*66.00 FL
17	1		*REAR BOOTLID C&C EMBLEM	Necessary	56.00 FL	*56.00 FL
18	1		*REAR BOOTLID LOCK (UPPER)	Damaged	152.40 FL	*152.40 FL
19	1		*REAR BOOTLID LOCK (LOWER)	Not Necessary	98.20 FL	*- FL
20	1		*REAR BOOTLID INNER TRIM	Torn	242.20 FL	*242.20 FL
21	2		*REAR BOOTLID O/S & N/S REFLECTOR	Cracked	821.40 FL	*821.40 FL
22	2		*REAR BOOTLID O/S & N/S REFLECTOR SEALANT	Necessary	26.00 FL	*26.00 FL
23	2		*REAR BOOTLID O/S & N/S HINGES	Bent	287.20 FL	*287.20 FL
24	1		*REAR BOOTLID CENTRE REFLECTOR	Cracked	438.00 FL	*438.00 FL
25	1		*REAR BUMPER REINFORCEMENT	Distorted	436.80 FL	*436.80 FL
26	2		*REAR BUMPER REINFORCEMENT O/S & N/S BRACKET	Dented	175.60 FL	*175.60 FL
27	2		*REAR ENFORCEMENT O/S & N/S RETAINER	Not Necessary	82.20 FL	*- FL
28	1		*REAR END PANEL	Distorted	480.50 FL	*480.50 FL
29	1		*REAR END PANEL INNER TRIM	Deformed	87.30 FL	*87.30 FL
30	1		*REAR SPARE WHEEL BOARD COVER	Not Necessary	296.70 FL	*- FL
31	2		*REAR N/S & O/S TAIL LAMP PANEL	Dented	330.60 FL	*330.60 FL
32	2		*REAR N/S & O/S TAIL LAMP GARNISH	Cut	86.40 FL	*86.40 FL
33	2		*REAR O/S & N/S FENDER	Buckled	2,710.00 FL	*2,710.00 FL
34	2		*REAR O/S & N/S FENDER INNER TRIM	Torn	709.40 FL	*709.40 FL
35	2		*REAR O/S & N/S WHEEL GUARD	Not Necessary	265.40 FL	*- FL
36	1		*REAR O/S FENDER AIR VENT	Not Necessary	126.00 FL	*- FL
37	1		*REAR WINDSCREEN	Cut	950.00 FL	*950.00 FL
38	2		*REAR QUARTER GLASS MOULDING	Necessary	160.40 FL	*160.40 FL
39	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
40	2		*REAR O/S & N/S TAIL LAMP SEAL	Necessary	20.00 FS	*20.00 FS
41	4		*REAR O/S & N/S TAIL LAMP CLIPS	Necessary	12.00 FS	*12.00 FS
42	8		*REAR BOOTLID INNER TRIM CLIPS	Necessary	24.00 FS	*24.00 FS
43	4		*REAR BOOTLID O/S & N/S REFLECTOR CLIPS	Necessary	12.00 FS	*12.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	4		*REAR BOOTLID CENTRE REFLECTOR CLIPS	Necessary	12.00 FS	*12.00 FS
45	16		*REAR N/S & O/S FENDER INNER TRIM CLIPS	Necessary	48.00 FS	*48.00 FS
46	1		*REAR O/S & N/S WHEEL GUARD CLIPS (22 PCS)	Not Necessary	66.00 FS	*- FS
47	1		*REAR WINDSCREEN SOLAR FILM	Cut	300.00 FS	*200.00 FS
48	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
49	1		*REAR WINDSCREEN MOULDING	Necessary	230.30 FS	*230.30 FS
50	2		*REAR QUARER GLASS SEALANT	Necessary	160.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,186.80	13,460.20
- List Item Discount on L Items 10.00/10.00% (S\$)	1,522.25	1,277.19
Total Parts (S\$)	14,664.55	12,183.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE REAR DAMAGED PARTS ,STRAIGHTEN & WELDING	New	1,800.00	1,500.00
2	TO SPRAY PAINTING	New	2,200.00	1,400.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE & REFIT REAR O/S & N/S QUARTER GLASS	New	160.00	80.00
5	TO REMOVE ROOF LINING & REAR SEAT TO FACILITATE REPAIR	New	160.00	80.00
6	TO REMOVE AND REPLACE REAR BOOT COVER FITTING	New	80.00	60.00
7	TO CHECK FOR FAULT CODE AND RESETTNG	New	150.00	0.00
8	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	60.00	50.00
9	TO CHECK WIRING	New	60.00	30.00
10	TO RE-SEAL ANTI-RUST	New	150.00	100.00
Gross Labour Cost (S\$)			4,970.00	3,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >