

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007419/UPA3Q2**Date:** 04/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100475544
Claimant Vehicle No :	SNA4356B	Insured Vehicle No :	SLE6012H
Date of Loss:	02/08/2022	Nature of Claim:	TP
		Claim No:	5426683476SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA4356B	Engine No:	F3671448B38B15A
Make & Model:	BMW 318I, 1.5 SEDAN LED NAV (A)	Chassis No:	WBA8E36080NU32168
Reg. Date:	14/10/2016 (Man. Year: 2016)	Odometer:	80884 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,977.19	2,535.92	2,441.27	49.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,135.00	870.00	1,265.00	59.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,112.19	3,405.92	3,706.27	52.11
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	7,112.19	2,700.00	4,412.19	62.04
+ GST 7.00/7.00% (S\$)	497.85	189.00	308.85	62.04
Nett Amount (S\$)	7,610.04	2,889.00	4,721.04	62.04
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,105.00		

INSPECTION

Date of Assignment:	08/08/2022	Inspected At:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Date Inspected:	08/08/2022		
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Dented	1,184.55 F	*1,184.55 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*REAR BUMPER REFLECTOR LH	Not Necessary	48.30 F	*- FL
4	2		*REAR BUMPER SENSOR	Shorted	561.90 F	*561.90 FL
5	1		*REAR BUMPER SPONGE	Not fitted	73.55 F	*- FL
6	1		*REAR BUMPER SPONGE CENTRE	Not fitted	175.80 F	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	477.30 F	*477.30 FL
8	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	185.80 F	*- FL
9	1		*REAR BUMPER EXHAUST SILENCER ASSY	Repair	1,040.70 F	*- FL
10	1		*REAR BUMPER EXHAUST CLAMPING BUSH	Not Necessary	80.70 F	*- FL
11	1		*REAR END PANEL	Repair	622.95 F	*- FL
12	1		*REAR END PANEL SEALER	Not Necessary	80.00 FS	*- FS
13	1		*REAR BUMPER MOULDING (BLACK)	Cut	105.64 F	*105.64 FL
14	1		*REAR BUMPER GUIDE CENTRE	Cracked	211.30 F	*211.30 FL
15	1		*EXTERNAL ANTENNA	Cracked	98.70 F	*98.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,977.19	2,669.39
- List Item Discount on L Items 0.00/5.00% (\$)	0.00	133.47
Total Parts (\$)	4,977.19	2,535.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT RENEW KNOCKING & WELDING REAR END PANEL ,REMOVE & INSTALL ALL DAMAGE PARTS STRAIGHTEN & REALIGN BODY	New	880.00	400.00
2	TUFF-KOTE ON DAMAGE PARTS	New	40.00	0.00
3	SPRAY PAINTING ON DAMAGE PARTS	New	680.00	400.00
4	REMOVE & REFIX REAR EXHAUST SILENCER ASSY	New	100.00	0.00
5	REMOVE & REFIX REAR BUMPER SENSOR	New	100.00	50.00
6	CHECK ALL LIGHTING AFTER REPAIRS	New	35.00	20.00
7	DIAGNOSTIC & RESET	New	300.00	0.00
			Gross Labour Cost (S\$)	2,135.00
				870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >