

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007424/AYA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800034026
Claimant Vehicle No :	SML6462T	Insured Vehicle No :	SLX7746S
Date of Loss:	02/08/2022	Nature of Claim:	TP
		Claim No:	5818224373SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML6462T	Engine No:	L15B5565672
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11315660
Reg. Date:	29/05/2019 (Man. Year: 2018)	Odometer:	65952 km
Colour:	Maroon		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,420.10	11,709.20	4,710.90	28.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,080.00	3,290.00	1,790.00	35.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,500.10	14,999.20	6,500.90	30.24
Approved Total (Overridden) (S\$)		12,000.00		
Nett Amount (S\$)	21,500.10	12,000.00	9,500.10	44.19
+ Loss of Use (14.0 x S\$60.00/day) (S\$)		840.00		
Nett Liability (S\$)		12,840.00		

INSPECTION

Date of Assignment:	03/08/2022	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.
Date Inspected:	03/08/2022 Inspected At:	
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	745.90 F	*745.90 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*REAR BUMPER SIDE HOLDER RH	Damaged	32.90 F	*32.90 FL
4	1		*REAR BUMPER REFLECTOR RH	Cracked	141.10 F	*141.10 FL
5	1		*TAILLAMP RH	Cracked	495.20 F	*495.20 FL
6	1		*TAILLAMP LOWER APRON RH	Distorted	195.10 F	*195.10 FL
7	1		*REAR RH FENDER	Distorted	984.40 F	*984.40 FL
8	1		*REAR RH FENDER INNER SHIELD	Deformed	168.90 F	*168.90 FL
9	1		*REAR RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
10	1		*REAR RH FENDER ARC GARNISH	Distorted	205.20 F	*205.20 FL
11	1		*REAR RH FENDER ARC GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
12	1		*REAR RH FENDER AIR VENT	Deformed	96.50 F	*96.50 FL
13	1		*REAR RH FENDER INNER TRIM	Deformed	305.40 F	*305.40 FL
14	1		*REAR RH FENDER INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
15	1		*REAR RH DOOR	Repair	1,108.20 F	*- FL
16	1		*REAR END PANEL	Repair	585.40 F	*- FL
17	1		*REAR RH WHEEL RIM	Cut	700.00 FS	*500.00 FS
18	1		*REAR RH TYRE	Punctured	280.00 FS	*180.00 FS
19	1		*REAR AXLE	Bent	1,513.20 F	*1,513.20 FL
20	1		*REAR RH SHOCK ABSORBER	Damaged	330.90 F	*330.90 FL
21	1		*REAR RH WHEEL HUB C/W BEARING	Damaged	363.90 F	*363.90 FL
22	1		*REAR EXHAUST PIPE	Dented	645.70 F	*645.70 FL
23	1		*ROOF AIR BAG RH	Activated	1,588.10 F	*1,588.10 FL
24	1		*ROOF AIR BAG SENSOR	Activated	240.40 F	*240.40 FL
25	1		*DRIVER SEAT AIR BAG	Activated	1,041.40 F	*1,041.40 FL
26	1		*DRIVER SEAT AIR BAG SENSOR	Activated	230.50 F	*230.50 FL
27	2		*FRONT SEAT BELT	Activated	1,379.20 F	*1,379.20 FL
28	1		*ROOF INNER TRIM BOARD	Torn	1,050.20 F	*1,050.20 FL
29	1		*ROOF INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
30	1		*AIR BAG ECU	Activated	982.40 F	*982.40 FL
31	1		*DRIVER SEAT CUSHION	Torn	850.00 FS	*680.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,420.10	14,256.50
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	2,547.30
Total Parts (\$)	16,420.10	11,709.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	80.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO TRANSFER REAR DOOR FITTINGS	New	150.00	0.00
8	TO REMOVE REAR UNDERCARRIAGE	New	380.00	320.00
9	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
10	TO REMOVE ROOF INNER TRIM BOARD	New	250.00	150.00
11	TO REMOVE AIR BAGS	New	450.00	350.00
12	TO REMOVE SEAT BELTS	New	200.00	150.00
13	TO REMOVE DRIVER SEAT CUSHION	New	200.00	100.00
14	TO RESET AIR BAG SETTINGS	New	400.00	300.00
Gross Labour Cost (S\$)			5,080.00	3,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >