

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007425/EVCE2**Date:** 30/11/2022**REFERENCE**

Insured/Claimant:	LEE MEI FEI	Policy No:	7220065304	Claim No:	0843559040SG
Date of Loss:	31/07/2022	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE798M	Engine No:	DEM034540
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF59NA002235
Reg. Date:	13/06/2022 (Man. Year: 2021)	Odometer:	2744 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$210,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 4 mm	Rear Left Side:	Hankook 4 mm
Front Right Side:	Hankook 4 mm	Rear Right Side:	Hankook 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,123.00	18,552.96	19,570.04	51.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,424.00	9,839.00	9,585.00	49.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	57,547.00	28,391.96	29,155.04	50.66
- Excess (S\$)	900.00	900.00	0.00	0.00
(S\$)	56,647.00	27,491.96	29,155.04	51.47
+ GST 7.00/7.00% (S\$)	3,965.29	1,924.44	2,040.85	51.47
Nett Amount (S\$)	60,612.29	29,416.40	31,195.89	51.47

INSPECTION

Date of Assignment:	04/08/2022	
Date Inspected:	03/08/2022	Inspected At: 24 Benoi Sector Singapore 629857 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	11.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,493.00 FS	*1,994.40 FS
2	2		*FRONT BUMPER SECURING STRIP	Bent	79.00 FS	*63.20 FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	293.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	599.00 FS	*- FS
6	1		*FRONT AIR GUIDE - RH	Crushed	72.00 FS	*57.20 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	293.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	151.00 FS	*120.40 FS
9	2		*FRONT BUMPER AIR GUIDE TRIM - RH / CENTER	Cut	181.00 FS	*82.64 FS
10	1		*RADIATOR GRILLE	Crushed	1,881.00 FS	*1,504.80 FS
11	1		*RADIATOR GRILLE COVER	Not Necessary	141.00 FS	*- FS
12	1		*RADIATOR GRILLE BRACKET	Not Necessary	19.00 FS	*- FS
13	1		*FRONT SECURING PLATE	Not Necessary	12.00 FS	*- FS
14	1		*FRONT CAMERA	Not Necessary	1,264.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	163.00 FS	*130.40 FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	899.00 FS	*719.20 FS
17	1		*FRONT BUMPER UPPER GUIDE SECTION - RH	Broken	41.00 FS	*32.24 FS
18	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
19	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
20	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
21	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	154.00 FS	*- FS
22	2		*FRONT BUMPER SUPPORT - LH / RH	Necessary	64.00 FS	*51.04 FS
23	4		*POP RIVET	Necessary	4.00 FS	*2.88 FS
24	1		*HORN LOW TONE - RH	Not Necessary	139.00 FS	*- FS
25	1		*HORN BRACKET - RH	Not Necessary	33.00 FS	*- FS
26	1		*FRONT PARKING AID SENSOR - OUTER / INNER / SIDE (3PCS)	Missing (1pc only)	798.00 FS	*212.40 FS
27	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
28	1		*SET FRONT BUMPER WIRING	Not Necessary	449.00 FS	*- FS
29	1		*FRONT FENDER - RH	Dented	1,189.00 FS	*951.20 FS
30	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
31	1		*FRONT FENDER CLOSING ELEMENT - RH	Bent	83.00 FS	*65.84 FS
32	1		*FRONT FENDER BRACKET - RH	Bent	41.00 FS	*32.72 FS
33	1		*POP RIVET (6PCS)	Necessary	23.00 FS	*18.24 FS
34	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	Not Necessary	55.00 FS	*- FS
35	1		*FRONT FENDER BRACKET - LH	Not Necessary	40.00 FS	*- FS
36	1		*FRONT FENDER BRACE - RH	Bent	132.00 FS	*105.20 FS
37	1		*FRONT FENDER TRIM - RH	Necessary	171.00 FS	*136.40 FS
38	1		*FRONT FENDER WHEEL HOUSING LINER - RH	Missing	299.00 FS	*238.80 FS
39	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	176.00 FS	*- FS
40	1		*FRONT WHEEL SPOILER - RH	Broken	82.00 FS	*65.12 FS
41	1		*FRONT SPOILER TRIM - RH	Not Necessary	40.00 FS	*- FS
42	1		*FRONT STONE CHIP GUARD - RH	Necessary	57.00 FS	*45.28 FS
43	1		*FRONT WHEEL SPOILER TRIM BRACKET TRIM - RH	Not Necessary	27.00 FS	*- FS
44	1		*FRONT FENDER LEDGE COVER - LONG	Broken	40.00 FS	*31.44 FS
45	1		*FRONT FENDER LEDGE COVER - RH SHORT	Necessary	18.00 FS	*13.92 FS
46	1		*HEADLIGHT TOP COVER - RH	Broken	49.00 FS	*38.64 FS
47	1		*BONNET	Dented	3,491.00 FS	*2,792.80 FS
48	1		*BONNET ATTACHMENT PARTS	Not Necessary	128.00 FS	*- FS
49	2		*BONNET HINGE - LH / RH	Not Necessary	932.00 FS	*- FS
50	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
51	1		*BONNET ENGINE SOUND ABSORBER	Crushed	382.00 FS	*305.60 FS
52	1		*FRONT FENDER COVER - RH INNER	Not Necessary	81.00 FS	*- FS
53	2		*BONNET GAS FILLED STRUT	Not Necessary	256.00 FS	*- FS
54	1		*BONNET STRIKER - RH	Not Necessary	56.00 FS	*- FS
55	1		*BONNET LID LOCK	Not Necessary	228.00 FS	*- FS
56	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
57	1		*BONNET BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
58	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
59	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
60	1		*BONNET LOCK CABLE - RH	Not Necessary	82.00 FS	*- FS
61	1		*FRONT PLENUM CHAMBER COVER - RH	Not Necessary	108.00 FS	*- FS
62	1		*HEADLIGHT MATRIX BEAM - RH	Broken	8,172.00 FS	*6,537.60 FS
63	1		*HEADLIGHT HOSE	Torn	42.00 FS	*32.88 FS
64	3		*HEADLIGHT COMPENSATING PIECE	Not Necessary	137.00 FS	*- FS
65	1		*LIFT CYLINDER - RH	Not Necessary	217.00 FS	*- FS
66	1		*LIFT CYLINDER BRACKET - RH	Broken	17.00 FS	*12.88 FS
67	2		*LIFT CYLINDER HOSE	Broken	160.00 FS	*127.60 FS
68	1		*WASH WATER RESERVOIR	Not Necessary	154.00 FS	*- FS
69	1		*LOCK CARRIER	Crushed	1,127.00 FS	*901.60 FS
70	1		*LOCK CARRIER SUPPORT - RH	Not Necessary	43.00 FS	*- FS
71	1		*CHARGE AIR COOLER	Not Necessary	654.00 FS	*- FS
72	1		*CHARGE AIR FOOLER PRESSURE HOSE - RH	Not Necessary	413.00 FS	*- FS
73	1		*A/C CONDENSER	Not Necessary	683.00 FS	*- FS
74	1		*A/C CONDENSER BRACKET	Not Necessary	21.00 FS	*- FS
75	1		*RADIATOR	Not Necessary	699.00 FS	*- FS
76	1		*RADIATOR FAN RING	Not Necessary	277.00 FS	*- FS
77	1		*RADIATOR CONTROL UNIT FAN	Not Necessary	2,012.00 FS	*- FS
78	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	72.00 FS	*- FS
79	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	38.00 FS	*- FS
80	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	44.00 FS	*- FS
81	6		*RADIATOR COOLANT	Necessary	297.00 FS	*237.12 FS
82	1		*INTAKE AIR DUCT - RH	Not Necessary	25.00 FS	*- FS
83	1		*INTAKE AIR DUCT AIR GUIDE	Not Necessary	61.00 FS	*- FS
84	1		*INTAKE AIR DUCT AIR FILTER	Broken	418.00 FS	*334.40 FS
85	1		*INTAKE AIR DUCT HOSE	Not Necessary	110.00 FS	*- FS
86	1		*FRONT DOOR CHROME TRIM - RH	Not Necessary	171.00 FS	*- FS
87	1		*NOISE INSULATION - LOWER CENTER	Not Necessary	640.00 FS	*- FS
88	1		*ROOF CHROME MOLDING - RH	Not Necessary	706.00 FS	*- FS
89	1		*FRONT WINDOW SLOT SEAL CHROME TRIM	Not Necessary	446.00 FS	*- FS
90	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
91	1		*SUNDRIES	Necessary	500.00 FS	*8.48 FS
92	1		*FRONT FENDER CONNECTING PLATE-RH UPPER (Supplementary)	Bent	279.00 FS	*222.80 FS
93	1		*FRONT FENDER CONNECTING PLATE-RH LOWER (Supplementary)	Bent	241.00 FS	*192.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **38,123.00** **18,552.96**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,600.00	1,600.00
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR RHS FRONT DOOR	New	280.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT AND RHS UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	3,000.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, RHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT, RHS UPPER A-PILLAR AND RHS FRONT DOOR	New	6,000.00	1,925.00
7	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
9	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
10	TO CUT AND WELD RHS FRONT FENDER TOP SUPPORT (Supplementary)	New	2,400.00	1,000.00
Gross Labour Cost (\$\$)			19,424.00	9,839.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >