

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22007426/UNY3Q2**Date:** 15/08/2022REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00065082201

**Claimant Vehicle  
No :** SKD3021T**Insured  
Vehicle No :** GBG2141C

Date of Loss: 02/08/2022

Nature of Claim: TP

Claim  
No: SNM22D205430/02/TANCHCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKD3021T**

Make &amp; Model: TOYOTA WISH, 1.8 CVT (A)

Engine No: 2ZRA782772

Reg. Date: 17/11/2011 (Man. Year: 2011)

Chassis No: JTDGG20W405002167

Colour: Brown

Odometer: 168845 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Tourador 6 mm

Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side: Tourador 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,183.47	3,657.80	1,525.67	29.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,790.00	880.00	32.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,853.47</b>	<b>5,447.80</b>	<b>2,405.67</b>	<b>30.63</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,350.00</b>		
<b>(S\$)</b>	7,853.47	4,350.00	3,503.47	44.61
<b>+ GST 7.00/7.00% (S\$)</b>	549.74	304.50	245.24	44.61
<b>Nett Amount (S\$)</b>	<b>8,403.21</b>	<b>4,654.50</b>	<b>3,748.71</b>	<b>44.61</b>

INSPECTION

Date of Assignment: 03/08/2022

Date Inspected: 04/08/2022

Inspected At:

Tan Lim Motor Pte Ltd (Defu)

1 Defu Lane 6

Singapore 539365

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2022)
<b>Parts:</b> M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKD3021T)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Dented / Bent	1,415.50 FL	*1,415.50 FL
2	1		*TAILGATE LID CENTRE LOGO	Necessary	50.80 FL	*50.80 FL
3	1		*TAILGATE LID OUTER CHROME GARNISH	Cracked	398.90 FL	*398.90 FL
4	1		*TAILGATE LID INNER TRIMBOARD	Serviceable	348.80 FL	*- FL
5	1		*TAILGATE LID INNER LOCK	Dented / Shorted	470.40 FL	*416.40 FL
6	1		*TAILGATE LID INNER WEATHERSTRIP	Twisted	322.30 FL	*322.30 FL
7	1		*REAR WINDSCREEN MOULDING	Necessary	180.00 FL	*145.10 FL
8	1		*O/S REAR LAMP	Not Necessary	638.20 FL	*- FL
9	6		*O/S REAR LAMP CLIPS	Not Necessary	27.00 FL	*- FL
10	1		*REAR BUMPER	Deformed / Torn	518.70 FL	*518.70 FL
11	2		*REAR BUMPER BRACKET	Repair	102.00 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	97.60 FL	*97.60 FL
13	8		*REAR BUMPER FASTENER CLIPS	Necessary	36.00 FL	*36.00 FL
14	1		*REAR END PANEL	Dented / Bent	515.10 FL	*515.10 FL
15	1		*REAR END PANEL INNER TRIM	Twisted	292.50 FL	*292.50 FL
16	8		*REAR END PANEL INNER TRIM CLIPS	Not Necessary	36.00 FL	*- FL
17	1		*REAR EXHAUST BOX	Repair	780.00 FL	*- FL
18	1		*REAR ANTENNA SENSOR	Cracked	241.50 FL	*241.50 FL
19	1		*SET REAR BUMPER PARKING SENSOR	Shorted	200.00 FS	*200.00 FS
20	1		*REAR LICENCE PLATE	Bent	40.00 FS	*40.00 FS
21	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
22	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>6,801.30</b>	<b>4,770.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,617.83	1,112.60
<b>Total Parts (\$)</b>	<b>5,183.47</b>	<b>3,657.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	40.00	20.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	50.00	50.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	100.00	80.00
5	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	100.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST BOX	New	80.00	0.00
7	TO RUST-PROOFING OF THE AFFECTED AREAS	New	80.00	60.00
8	PUTTY & SPRAY PAINTING OF THE AFFECTED PORTION	New	1,000.00	800.00
9	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,100.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>2,670.00</b>	<b>1,790.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**