

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA22007428/KCY3Q2**Date:** 20/02/2023**REFERENCE**

Insured/Claimant:	PHANG BOO CHYE	Policy No:	MP319712	
Date of Loss:	22/07/2022	Nature of Claim:	OD	Claim No: MPC03563/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV9454G	Engine No:	HR12275180B
Make & Model:	NISSAN NOTE, 1.2 (A)	Chassis No:	JN1TAAE12Z0980160
Reg. Date:	24/01/2018 (Man. Year: 2017)	Odometer:	65125 km
Colour:	Blue		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,004.20	2,146.10	2,858.10	57.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	1,930.00	860.00	30.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,794.20	4,076.10	3,718.10	47.70
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	7,794.20	3,576.10	4,218.10	54.12
+ GST 7.00/7.00% (S\$)	545.59	250.33	295.26	54.12
Nett Amount (S\$)	8,339.79	3,826.43	4,513.36	54.12

INSPECTION

Date of Assignment:	03/08/2022	Present Location:	Ah Lim Motor Company (Sin Ming)
Date Inspected:	08/08/2022	Inspected At:	Ah Lim Motor Company (Sin Ming) 176 Sin Ming Drive #05-12, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,023.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2023)
Parts:	144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV9454G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE (WCP)	Buckled	950.00 F	*950.00 F
2	1		*TAILGATE RUBBER SEAL (WCP)	Deformed	65.00 F	*65.00 F
3	2		*TAILGATE HINGE LH/RH (WCP)	Repair	96.00 F	*- F
4	1		*TAILGATE NO PLATE LAMP GARNISH (WCP)	Cut	190.00 F	*190.00 F
5	1		*TAILGATE INNER LOCK (WCP)	Damaged	110.00 F	*110.00 F
6	1		*NOTE BADGE (WCP)	Necessary	58.00 F	*58.00 F
7	1		*NISSAN BADGE (WCP)	Necessary	58.00 F	*58.00 F
8	2		*NO PLATE LAMP LH/RH (WCP)	Not Necessary	60.00 F	*- F
9	1		*REAR BUMPER (WCP)	Dented	320.00 F	*320.00 F
10	2		*REAR BUMPER SIDE RETAINER LH/RH (WCP)	Serviceable	56.00 F	*- F
11	1		*REAR BUMPER INNER SPONGE (WCP)	*Check	90.00 F	*- F
12	1		*REAR WIPER MOTOR (WCP)	Not Necessary	469.00 F	*- F
13	1		*REAR WIPER ARM BLADE (WCP)	Not Necessary	60.00 F	*- F
14	1		*REAR BUMPER REINFORCMENT RH (WCP)	*Check	45.00 F	*- F
15	1		*REAR KEYLESS ANTENNA (WCP)	*Check	65.00 F	*- F
16	1		*TAIL END PANEL (WCP)	*Check	320.00 F	*- F
17	1		*TAIL END PANEL INNER TRIM BOARD (WCP)	*Check	70.00 F	*- F
18	1		*REAR FENDER RH INNER TRIM BOARD (WCP)	*Check	340.00 F	*- F
19	1		*REAR WINDSCREEN (WCP)	Serviceable	900.00 F	*- F
20	1		*REVERSE SENSOR	Damaged	220.00 FS	*220.00 FS
21	2		*WINDSCREEN SEALANT	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,572.00	1,971.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	432.20	175.10
Total Parts (\$\$)	5,004.20	2,146.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND REFOCUS TAILLAMP	New	30.00	30.00
2	TO DISMANTLE AND INSTALL REAR WINDSCREEN	New	120.00	80.00
3	TO DISMANTLE AND TRANSFER TAILGATE INNER PARTS; WIRING HARNESS AND TRIM BOARD	New	60.00	60.00
4	TO DISMANTLE AND INSTALL ROOF TOP LINING; CENTRE PILLER INNER TRIM BOARD FOR KNOCK AND REPAIR ROOF TOP PANEL	New	80.00	60.00
5	TO DISMANTLE AND REPLACE DAMAGE PARTS; TO CUT; KNOCK AND WELD TAIL END PANEL; KNOCK AND REPAIR ROOF TOP PANEL; REAR FENDER RH AND AFFECTED AREA	New	1,200.00	900.00
6	TO SPRAY TAIL GATE; REAR BUMPER; REAR FENDER RH; ROOF TOP PANEL; REAR FENDER LH AND TAIL END PANEL	New	1,300.00	800.00
Gross Labour Cost (S\$)			2,790.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >