

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007431/ACM4**Date:** 29/11/2022**REFERENCE**

Insured/Claimant:	TAN YEN WEN	Policy No:	7210122019		
Date of Loss:	07/07/2022	Nature of Claim:	OD	Claim No:	4239097441SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB6592S		Engine No:	DFY295068
Make & Model:	AUDI A3, 1.5 SEDAN TFSI S TRONIC (18") (A)		Chassis No:	WAUZZZGY6NA006493
Reg. Date:	03/09/2021 (Man. Year: 2021)		Odometer:	19802 km
Colour:	White			
Engine Capacity:	1498 cc			
Market Value/New Car Price:	S\$160,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,414.00	3,403.60	9,010.40	72.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	2,522.00	2,600.00	50.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,536.00	5,925.60	11,610.40	66.21
+ GST 7.00/7.00% (S\$)	1,227.52	414.79	812.73	66.21
Nett Amount (S\$)	18,763.52	6,340.39	12,423.13	66.21

INSPECTION

Date of Assignment:	04/08/2022		
Date Inspected:	03/08/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	1,677.00 FS	*- FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	290.00 FS	*- FS
3	1	*FRONT BUMPER S-LINE CLOSING ELEMENT - LH	Not Necessary	130.00 FS	*- FS
4	1	*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	433.00 FS	*- FS
5	1	*FRONT BUMPER PLATE CLOSING ELEMENT - LOWER CENTRE	Not Necessary	265.00 FS	*- FS
6	1	*FRONT BUMPER AIR GUIDE - LH	Not Necessary	67.00 FS	*- FS
7	1	*FRONT BUMPER COVER TRIM - LH	Not Necessary	104.00 FS	*- FS
8	1	*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	171.00 FS	*136.40 FS
9	1	*FRONT SUPPORT - LH	Not Necessary	43.00 FS	*- FS
10	1	*RADIATOR GRILLE	Not Necessary	932.00 FS	*- FS
11	1	*FRONT END PLATE CLOSING ELEMENT - CENTER	Not Necessary	210.00 FS	*- FS
12	1	*FRONT CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
13	1	*FRONT STICKER FOR AIR CONDITIONER	Not Necessary	9.00 FS	*- FS
14	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	120.00 FS	*- FS
15	1	*FRONT BUMPER BEAM	Not Necessary	748.00 FS	*- FS
16	1	*FRONT SHIELD COVER	Not Necessary	93.00 FS	*- FS
17	1	*FRONT BUMPER GUIDE - LH	Not Necessary	54.00 FS	*- FS
18	1	*FRONT LOW TONE SIGNAL HORN - LH	Not Necessary	153.00 FS	*- FS
19	1	*FRONT SPRING SHACKLE - LH	Not Necessary	35.00 FS	*- FS
20	2	*FRONT SPRING SHACKLE	Not Necessary	54.00 FS	*- FS
21	1	*FRONT FENDER - LH	Repair	1,241.00 FS	*- FS
22	4	*FRONT POP RIVET	Not Necessary	16.00 FS	*- FS
23	1	*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	32.00 FS	*- FS
24	1	*FRONT FENDER BRACE - LH	Not Necessary	98.00 FS	*- FS
25	1	*FRONT FENDER BRACKET - LH	Not Necessary	46.00 FS	*- FS
26	1	*FRONT FENDER WHEEL HOUSING LINER- LH	Not Necessary	183.00 FS	*- FS
27	1	*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	22.00 FS	*- FS
28	1	*FRONT LED HEADLIGHT - LH	Cut	4,084.00 FS	*3,267.20 FS
29	1	*FRONT HOSE - LH	Not Necessary	28.00 FS	*- FS
30	1	*FRONT HEADLIGHT LIFT CYLINDER - LH	Not Necessary	211.00 FS	*- FS
31	1	*FRONT HOSE	Not Necessary	108.00 FS	*- FS
32	1	*FRONT SENSOR AIR GUIDE GRILLE - OUTER	Not Necessary	279.00 FS	*- FS
33	1	*FRONT PARKING AID SENSOR (TBC) (NPA)	Not Necessary	0.00 FS	*- FS
34	4	*FRONT SEAL RING	Not Necessary	32.00 FS	*- FS
35	1	*SUNDRIES	Not Necessary	350.00 FS	*- FS
36	1	*FRONT NO PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 12,414.00 3,403.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,122.00	2,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >