

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007432/APA3Q2**Date:** 10/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000127
Claimant Vehicle No :	SLJ2232P	Insured Vehicle No :	SNE6360D
Date of Loss:	29/07/2022	Nature of Claim:	TP
		Claim No:	7349261136SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ2232P	Engine No:	1NZX702038
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305050277
Reg. Date:	24/03/2008 (Man. Year: 2008)	Odometer:	216587 km
Colour:	Blue		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,384.12	6,722.85	7,661.27	53.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,880.00	3,310.00	2,570.00	43.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,264.12	10,032.85	10,231.27	50.49
Approved Total (Overridden) (S\$)		5,900.00		
Nett Amount (S\$)	20,264.12	5,900.00	14,364.12	70.88
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		6,538.45		

INSPECTION

Date of Assignment:	01/08/2022	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	01/08/2022 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	9.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	575.00 FL	*575.00 FL
2	1		*BOOT LID LOGO	Necessary	70.00 FL	*70.00 FL
3	1		*BOOT LID EMBLEM VIOS	Necessary	65.00 FL	*65.00 FL
4	1		*BOOT LID EMBLEM E	Necessary	55.00 FL	*55.00 FL
5	1		*BOOT LID OUTER MOULDING	Deformed	190.00 FL	*190.00 FL
6	2		*BOOT LID NUMBER PLATE LAMP	Not Necessary	84.00 FL	*- FL
7	1		*BOOT LID TOP LOCK	Damaged	155.00 FL	*155.00 FL
8	1		*BOOT LID LOWER LOCK	Necessary	25.00 FL	*25.00 FL
9	1		*BOOT LID KEY LOCK	Not Necessary	225.00 FL	*- FL
10	1		*BOOT LID WEATHER STRIP	Cut	205.00 FL	*205.00 FL
11	2		*BOOT LID HINGE	Not Necessary	140.00 FL	*- FL
12	1		*REAR BUMPER	Distorted	495.00 FL	*495.00 FL
13	1		*REAR BUMPER REFLECTOR	O/S Cracked	210.00 FL	*105.00 FL
14	1		*REAR BUMPER BRACKET	N/S Dented	178.00 FL	*89.00 FL
15	2		*REAR BUMPER SIDE RETAINER (FRONT)	Not Necessary	210.00 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINER (REAR)	Damaged	110.00 FL	*110.00 FL
17	2		*TAIL LAMP	Cracked	690.00 FL	*690.00 FL
18	1		*TAIL LAMP PANEL	O/S Dented	380.00 FL	*190.00 FL
19	1		*REAR FENDER	O/S Buckled	1,830.80 FL	*915.40 FL
20	2		*REAR FENDER INNER COWLING	Not Necessary	350.00 FL	*- FL
21	1		*REAR FENDER INNER TRIM	O/S Crumpled	590.00 FL	*295.00 FL
22	1		*REAR WINDSCREEN MOULDING	Necessary	90.40 FL	*90.40 FL
23	1		*REAR CHASSIS MEMBER RH	Repair	694.30 FL	*- FL
24	1		*REAR END PANEL	Dented	439.00 FL	*439.00 FL
25	1		*REAR END PANEL TOP GARNISH	Deformed	230.00 FL	*230.00 FL
26	1		*REAR FLOOR PANEL TOP BOARD	Torn	175.00 FL	*175.00 FL
27	2		*REAR FLOOR PANEL TOP SPONGE (SIDE)	Deformed	550.00 FL	*550.00 FL
28	1		*CENTER EXHAUST	Not Necessary	3,100.00 FL	*- FL
29	1		*CENTER EXHAUST INSULATOR	Not Necessary	95.00 FL	*- FL
30	1		*SET CENTER EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
31	4		*REAR EXHAUST MOUNTING	Not Necessary	180.00 FL	*- FL
32	1		*SET REAR EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
33	1		*REAR EXHAUST INSULATOR	Not Necessary	89.00 FL	*- FL
34	1		*REAR EXHAUST PIPE WITH BOX	Bent	690.00 FL	*690.00 FL
35	1		*REAR FLOOR PANEL	Buckled	840.00 FL	*840.00 FL
36	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
37	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
38	1		*SET BOOT LID OUTER MOULDING CLIP	Necessary	30.00 FS	*30.00 FS
39	1		*BOOT LID EMBLEM SPORT	Necessary	80.00 FS	*50.00 FS
40	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
41	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
42	1		*REAR SPOILER	Not Necessary	850.00 FS	*- FS
43	2		*REAR FENDER SEALANT	Necessary	300.00 FS	*60.00 FS
44	1		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
45	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	80.00 FS	*30.00 FS
46	1		*SET TAIL LAMP CLIPS	Necessary	30.00 FS	*30.00 FS
47	1		*REAR DIFFUSER	Distorted	1,000.00 FS	*600.00 FS
48	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
49	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
50	1		*REAR EXHAUST CHROME PIPE (SPECIAL TYPE)	Bent	250.00 FS	*120.00 FS
51	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
52	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **17,915.50** **8,533.80**
- List Item Discount on L Items 25.00/25.00% (\$\$) **3,531.38** **1,810.95**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	14,384.12 6,722.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD,CUT,KNOCK ,GRAZE ADJUST ,REPLACE NEW PARTS	New	2,200.00	1,600.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX ADJACENT PANELS	New	1,800.00	1,200.00
3	TUFF COAT	New	250.00	60.00
4	WIRING /BULB CHECKING	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	New	200.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
8	REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
9	REMOVE AND REFIX REAR EXHAUST	New	180.00	80.00
10	TRANSFER BOOT LID MECHANISM	New	80.00	60.00
11	REMOVE AND REFIX REAR SPOILER AND DIFFUSER	New	300.00	0.00
12	TO CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
13	REAR CHASSIS MEMBER ALIGHMENT	New	250.00	0.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			5,880.00	3,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >