

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22007434/DQY3E2

Date: 30/08/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001959615
Claimant Vehicle No :	SKB7587L	Insured Vehicle No :	SLG6508J
Date of Loss:	02/08/2022	Nature of Claim:	TP
		Claim No:	281111

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB7587L	Engine No:	G4KD9H525699
Make & Model:	KIA CERATO FORTE KOUP, 2.0 SX MT D/AB SR (A)	Chassis No:	KNAFW612LA5167810
Reg. Date:	27/06/2011 (Man. Year: 2009)	Odometer:	162742 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,395.90	7,162.49	7,233.41	50.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	2,140.00	2,120.00	49.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,655.90	9,302.49	9,353.41	50.14
Approved Total (Overridden) (S\$)		7,400.00		
Nett Amount (S\$)	18,655.90	7,400.00	11,255.90	60.33

INSPECTION

Date of Assignment:	04/08/2022	Alfred Auto Services & Supplies (HQ) Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2 Singapore 569538
Date Inspected:	04/08/2022 Inspected At:	
Estimated Period of Repair:	6.0 days	

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Aug 2022)

Parts: 143 KIA CERATO FORTE KOUP 2.0 SX MT D/AB SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKB7587L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	1,190.00 F	*962.00 FL
2	2		*FRONT BONNET HINGER	Repair	420.00 F	*- FL
3	1		*FRONT BONNET INNER SEAL	Serviceable	158.00 F	*- FL
4	1		*FRONT BONNET INNER SPONGE	Serviceable	310.00 F	*- FL
5	1		*FRONT BONNET LOCK	Bent	345.00 F	*85.00 FL
6	1		*FRONT BONNET STOPPER	Dislodged	18.50 F	*18.50 FL
7	1		*SUPPORT PANEL	Dented	989.30 F	*542.30 FL
8	2		*FRONT HEAD LAMP ASSY	Mtg Broken	2,260.00 F	*1,188.00 FL
9	1		*FRONT GRILLE (SPORT R)	Broken	480.00 FS	*480.00 FS
10	1		*FRONT BUMPER	Dented	968.00 F	*614.20 FL
11	2		*FRONT BUMPER SIDE RETAINER	Serviceable	378.00 F	*- FL
12	1		*FRONT BUMPER CENTRE PAD	Cut	510.00 F	*226.00 FL
13	1		*FRONT BUMPER CENTRE GRILLE	Mtg Cracked	305.00 F	*185.00 FL
14	1		*FRONT BUMPER FOG LAMP	Not Necessary	590.00 F	*- FL
15	1		*FRONT BUMPER FOG LAMP COVER O/S	Distorted / Cut	210.00 F	*172.00 FL
16	1		*FRONT LH FENDER	Dented	630.00 F	*385.00 FL
17	1		*FRONT LH FENDER DUST GARNISH	Not Necessary	299.00 F	*- FL
18	1		*FRONT BUMPER REINFORCEMENT	Dented	810.00 F	*306.00 FL
19	10		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*20.00 FS
20	1		*FRONT GRILLE CLIPS (8PCS)	Necessary	64.00 FS	*15.00 FS
21	1		*COOLANT	Not Necessary	90.00 F	*- FL
22	2		*HEAD LAMP LOWER BRACKET	Bent	160.00 F	*160.00 FL
23	1		*BUMPER SPONGE	Torn	299.00 F	*189.00 FL
24	2		*SUPPORT DUST GARNISH	Not Necessary	210.00 F	*- FL
25	1		*RADIATOR	Bent	995.00 F	*746.00 FL
26	1		*RADIATOR FAN ASSY	Broken	698.60 F	*698.60 FL
27	1		*AIR-CON CONDENSER	Bent / Punctured	610.00 F	*610.00 FL
28	1		*POWER STEERING RETURN PIPE	Bent	298.50 F	*298.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,395.90	7,901.10
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	738.61
Total Parts (\$)	14,395.90	7,162.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING, REFOCUS HEAD LAMP, REMOVE & REFIT ALL WIRE	New	150.00	30.00
2	TO REMOVE & REFIT RADIATOR, FAN, PIPE HOSE & ALL AFFECTED AREA	New	150.00	50.00
3	TO REMOVE & REFIT AIR-CON CONDENSER & TOP-UP GAS COMPRESSOR OIL	New	130.00	120.00
4	TO KNOCKING, STRAIGHTENING, REPAIR & RENEW ALL ACCIDENT	New	1,000.00	700.00
5	TO REDO CAR WRAP FROM EXISTING DESIGN (BONNET, FENDER & BUMPER)	New	1,200.00	600.00
6	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA	New	1,100.00	600.00
7	TO DIAGNOSTIC CHECK ON ALL SENSORS & ERASE FAULT CODE & SET TO STANDARD	New	380.00	0.00
8	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	150.00	40.00
Gross Labour Cost (\$\$)			4,260.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >