Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte.

Ltd.

4 Shenton Way

#21-01 SGX Centre 2 Singapore 068807 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Douglas Ong Chu Chong Date: 25 Aug 2022

Preliminary Advice

Insured: SLG6508J

Vehicle No

TP Vehicle : SKB7587L Accident Date : 02/08/2022

No . ORB/30/2

Make : KIA CERATO FORTE KOUP Assignment Date : 04/08/2022

Inspection Repair . O

Inspection At: ALFRED AUTO SERVICES & SUPPLIES (HQ)

BLK 5035, ANG MO KIO AVE 3, #01-351, ANG MO KIO

INDUSTRIAL PARK 2 SINGAPORE 569538

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 18,655.90 Revised Amount :S\$ 9,302.49 Check Items (Estimated) :S\$ 0.00 Total :S\$ 9,302.49

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$
Pre-Accident Value :S\$

COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

()	The vehicle is economical for repair
()	The vehicle is not economical for repair
()	Part-by-Part repair
(X)	Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.