

ASS. REC. BY: TaujiahREF: CS/1A1S22007435/T9J3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. 202222005914SLSum Insured: _____ Excess: 92000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 937K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMW 6867D Yr Regn: 2014 / NovType: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Subaru XV 1.6 C.C. 1600Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 96475 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF1GP3K CSE 9146675Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt or _____Brake: ☒ Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / ☒ Rim / STD A/Rim or _____Tyre Size: F: 225/355R17R: 2 -

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Umuho

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 4/8/22Survey held at KFS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

05/08/22 @ 6.39pm revert to Sharon Lim via Merimen.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

☐ : Interview (\$ _____)

Photos _____

☐ : Tech. Invs (\$ _____)

Others _____

☐ : Weekend (\$ _____)

TOTAL

Rep. Format: _____

Lump Sum / I.B.I. (\$) _____



簡福星噴漆工廠 KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 630147
Tel : (65) 6747 9550, 6358 2126, 6358 4361
Fax: (65) 6748 1006, 6281 8428
E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg. No. 221455-00E
GST Reg. No. M3-000533-E

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2000593898-01	Date of Loss:	01/08/2022
Vehicle Reg. No.:	SMM6867D	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHEW SWEE KIN KELVIN		
Make/Model:	SUBARU XV, 1.6 (A)	Vehicle Reg. Date:	28/11/2016
Vehicle Colour:	METALLIC BLUE		
Engine No:	FB161488713	Chassis No:	JF1GP3KC5EG146675
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	REMARK : THERE MIGHT PRICE DIFFERENT DUE TO NO STOCK		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

COST OF CLAIMS

	Amount
Parts	8,028.90
Miscellaneous Items	40.00
Labour	1,180.00
Paintwork Labour	1,100.00
Towing	0.00
Calculated Gross Total (S\$)	10,348.90
- Excess (S\$)	2,000.00
(S\$)	8,348.90
+ GST 7.00% (S\$)	584.42
Nett Amount (S\$)	8,933.32

This claim is handled by: MT TAN

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 03 Aug 2022)

Parts: 144

SUBARU XV 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SMM6867D/03/08/2022 14:52

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET	0.00	0.00	bt ✓ *370.00 F
2	1		*FRONT BONNET LOCK LOWER	0.00	0.00	bt ✓ *70.00 F
3	1		*FRONT BONNET LOCK TOP	0.00	0.00	bt ✓ *30.00 F
4	1		*FRONT BONNET INSULATOR	0.00	0.00	de ✓ *140.00 F
5	10		*FRONT BONNET INSULATYOR CLIP	0.00	0.00	rel ✓ *25.00 F
6	1		*FRONT BONNET HINGE RH	0.00	0.00	? *32.00 F
7	1		*FRONT BONNET HINGE LH	0.00	0.00	? *32.00 F
8	1		*FRONT SUPPORT PANEL	0.00	0.00	bt ✓ *330.00 F
9	1		*FRONT FENDER RH	0.00	0.00	bt ✓ *195.00 F
10	1		*FRONT FENDER LH	0.00	0.00	Rx ✓ *195.00 F
11	1		*FRONT FENDER SHIELD RH	0.00	0.00	fr ✓ *70.00 F
12	20		*FRONT FENDER SHIELD CLIP	0.00	0.00	ng ✓ *50.00 F
13	1		*FRONT FENDER WHEEL ARCH GARNISH RH	0.00	0.00	cut ✓ *125.00 F
14	1		*FRONT FENDER WHEEL ARCH GARNISH LH	0.00	0.00	X *125.00 F
15	1		*FRONT HEADLAMP RH	0.00	0.00	ew ✓ *560.00 F
16	1		*FRONT HEADLAMP LH	0.00	0.00	ew ✓ *560.00 F
17	1		*FRONT HEADLAMP LOWER BRACKET RH	0.00	0.00	dis ✓ *32.00 F
18	1		*FRONT HEADLAMP LOWER BRACKET LH	0.00	0.00	? *32.00 F
19	1		*FRONT HEADLAMP SIDE BRACKET RH	0.00	0.00	ov ✓ *35.00 F
20	1		*FRONT HEADLAMP SIDE BRACKET LH	0.00	0.00	? *35.00 F
21	1		*FRONT GRILLE	0.00	0.00	MS ✓ *100.00 F
22	1		*FRONT GRILLE CHROME TOP	0.00	0.00	MS ✓ *170.00 F
23	1		*FRONT GRILLE CHROME LOWER	0.00	0.00	MS ✓ *120.00 F
24	1		*FRONT GRILLE BRACKET	0.00	0.00	dy ✓ *30.00 F
25	1		*FRONT GRILLE EMBLEM60	0.00	0.00	rel ✓ *60.00 F
26	1		*FRONT BUMPER	0.00	0.00	fr ✓ *360.00 F
27	1		*FRONT BUMPER SIDE RETAINER RH	0.00	0.00	an ✓ *12.00 F
28	1		*FRONT BUMPER SIDE RETAINER LH	0.00	0.00	? *12.00 F
29	1		*FRONT BUMPER FOAM	0.00	0.00	an ✓ *60.00 F
30	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	ht ✓ *240.00 F
31	1		*FRONT B UMPER FOGLAMP RH	0.00	0.00	? *250.00 F
32	1		*FRONT BUMPER BRACKET RH	0.00	0.00	dy ✓ *22.00 F
33	1		*FRONT BUMPER LOWER GARNISH	0.00	0.00	? *55.00 F
34	10		*FRONT BUMPER CLIP	0.00	0.00	ng ✓ *25.00 F
35	1		*ENGINE UNDERCOVER	0.00	0.00	? *150.00 F
36	1		*HORN	0.00	0.00	bt ✓ *30.00 F
37	1		*AIR CON CONDENSER	0.00	0.00	bt ✓ *380.00 F
38	1		*AIR CON FAN ASSY	0.00	0.00	? *360.00 F
39	1		*AIR DUCT	0.00	0.00	? *45.00 F
40	1		*AIR CLEANER BOX TOP	0.00	0.00	? *55.00 F
41	1		*AIR CLEANER BOX LOWER	0.00	0.00	? *55.00 F
42	1		*RADIATOR	0.00	0.00	? *520.00 F
43	1		*RADIATOR TOP HOSE	0.00	0.00	an ✓ *35.00 F
44	1		*RADIATOR FAN COWLING	0.00	0.00	? *60.00 F
45	1		*RADIATOR FAN BLADE	0.00	0.00	? *45.00 F

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*RADIATOR FAN MOTOR	0.00	0.00	*180.00 F
47	1		*SPARE TANK	0.00	0.00	*60.00 F
48	1		*REAR DOOR RH	0.00	0.00	*550.00 F
49	3		*REAR DOOR FAME STICKER	0.00	0.00	*75.00 F
50	1		*REAR FENDER WHEEL ARCH GARNISH RH	0.00	0.00	*140.00 F

F=Franchise part.

Sub Total (S\$)	7,299.00
+ Margin on L,N Items 10.00% (S\$)	729.90
Total Parts (S\$)	8,028.90

Kan Fook Sing Motor Workshop/SMM6867D/03/08/2022 14:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 FRONT NUMBER PLATE

40.00

Sub Total (S\$)

40.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 SPRAYPAINTING CHARGES

New

900

1,100.00

Labour Items

2 TO CHECK WIRING SYSTEM

New

30

50.00

3 TO CHECK ALIGNMENT

New

80

100.00

4 TO REMOVE/REFIT/REFILL AIR CON GAS

New

✓

100.00

5 TO TRANSFER DOOR MECHANISM TO NEW DOOR

New

X

50.00

6 TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS

New

700

880.00

Gross Labour Cost (S\$)

2,280.00

Kan Fook Sing Motor Workshop/SMM6867D/03/08/2022 14:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanfik 97495749

WP Not Authorise Revert.

Ex \$2000 4/8/22 @ 1230pm

tanfik@lkhauto.com.

7 days.

* Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: