

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22007437/EQY3Q2**Date:** 27/09/2022**REFERENCE**

Insured/Claimant: LIM BOON KIAT, MELVIN (LIN WENJIE, MELVIN) Policy No: SP2000423805

Date of Loss: 01/08/2022

Nature of Claim: OD

Claim No: 202222005928SL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMU7997M**

Make & Model: VOLKSWAGEN SHARAN, 2.0 (A)

Engine No: DED035867

Reg. Date: 13/08/2020 (Man. Year: 2020)

Chassis No: VWWZZZ7NZLV013418

Colour: White

Odometer: 30903 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$165,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Pirelli 4 mm

Rear Left Side: Pirelli 4 mm

Front Right Side: Pirelli 4 mm

Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,644.17	11,488.50	155.67	1.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,115.00	8,005.00	4,110.00	33.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,759.17	19,493.50	4,265.67	17.95
+ GST 7.00/7.00% (S\$)	1,663.14	1,364.55	298.59	17.95
Nett Amount (S\$)	25,422.31	20,858.05	4,564.26	17.95

INSPECTION

Date of Assignment: 04/08/2022

Date Inspected: 04/08/2022 Inspected At:

Volkswagen Group Singapore Pte Ltd (tuas) (HQ)

17 Tuas Ave 9

Singapore 639197

Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2022)
Parts:	M1-MPV	VOLKSWAGEN SHARAN 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU7997M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER FOR BUMPER PRIMED	Crushed	1,554.00 FS	*1,554.00 FS
2	1	*FRONT SPOILER SATIN BLACK		130.13 FS	*- FS
3	1	*GUIDE PIECE LHS BUMPER SIDE BRACKET	Bent	32.17 FS	*32.17 FS
4	1	*GUIDE PIECE RHS BUMPER SIDE BRACKET	Broken	32.17 FS	*32.17 FS
5	1	*SUPPORT PART RHS NOZZLE BRACKET	Not Necessary	25.54 FS	*- FS
6	1	*COOLING AIR GRILLE SATIN B RHS FOG LAMP GRILLE	Cut	132.13 FS	*132.13 FS
7	1	*RADIATOR GRILLE SATIN BIA	Cut	519.39 FS	*519.39 FS
8	1	*HEADLAMPS FOR CURVE LIGHT	Broken	1,874.61 FS	*1,874.61 FS
9	1	*FENDER RH	Dented	514.12 FS	*514.12 FS
10	1	*CROSS SUPPORT RHS FENDER BRACKET	Bent	38.19 FS	*38.19 FS
11	1	*WHEELHOUSE LINER RHS FENDER LINER	Crushed	125.00 FS	*125.00 FS
12	1	*FENDER LH	Dented	514.12 FS	*514.12 FS
13	1	*DOOR LHS FRT DOOR	Dented	1,822.32 FS	*1,822.32 FS
14	1	*DOOR SEAL OUTER	Necessary	279.71 FS	*279.71 FS
15	1	*ALU-LAMIN INSULATION DOOR INSULATION	Necessary	31.43 FS	*31.43 FS
16	1	*BOLT WITH POLYGON SOCKET	Necessary	4.05 FS	*4.05 FS
17	1	*FILL HD SCREW (2 PCS)	Necessary	4.49 FS	*4.49 FS
18	1	*EXPANDING NUT (4 PCS)	Necessary	14.17 FS	*14.17 FS
19	1	*CLIP (4 PCS)	Necessary	9.30 FS	*9.30 FS
20	1	*COVER FOR DOOR PRIMED LHS FRT DOOR LOWER MLDG	Necessary	215.18 FS	*215.18 FS
21	1	*GROMMET (8 PCS)	Necessary	10.60 FS	*10.60 FS
22	1	*TRACK CONTROL ARM RHS LOWER ARM	Bent	367.65 FS	*367.65 FS
23	1	*BOLT HEX HD WITH SHOULD	Necessary	8.60 FS	*8.60 FS
24	1	*HEXAGON FLANGE SCREW	Necessary	7.27 FS	*7.27 FS
25	1	*BOLT HEX HD WITH SHOULD (2 PCS)	Necessary	8.67 FS	*8.67 FS
26	1	*GUIDE JOINT	Necessary	109.87 FS	*109.87 FS
27	1	*SHOULDERED HEX NUT (3 PCS)	Necessary	6.74 FS	*6.74 FS
28	1	*SHOULDERED HEX NUT	Necessary	4.27 FS	*4.27 FS
29	1	*WHEEL BEARING WITH MOUNTI	Necessary	446.08 FS	*446.08 FS
30	1	*WHEEL BEARING HOUSING	Bent	508.11 FS	*508.11 FS
31	1	*OVAL HEXAGON SOCKET HEAD	Necessary	6.23 FS	*6.23 FS
32	1	*SHOULDERED HEX NUT SELF	Necessary	2.59 FS	*2.59 FS
33	1	*SHOULDERED HEX NUT	Necessary	2.31 FS	*2.31 FS
34	1	*GAS-FILLED SHOCK ABSORBER	Bent	312.32 FS	*312.32 FS
35	1	*BALL BEARING TOP BEARING	Necessary	26.40 FS	*26.40 FS
36	1	*SUSPENSION STRUT MOUNTING TOP MTG	Necessary	100.99 FS	*100.99 FS
37	1	*SHOULDERED HEX NUT	Necessary	4.33 FS	*4.33 FS
38	1	*BOLT HEX HD (3 PCS)	Necessary	10.91 FS	*10.91 FS
39	1	*TIE ROD	Bent	83.08 FS	*83.08 FS
40	1	*TIE ROD END	Bent	106.14 FS	*106.14 FS
41	1	*SHOULDERED HEX NUT	Necessary	4.27 FS	*4.27 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
42	1	*RETAINING CLIP	Necessary	4.05 FS	*4.05 FS
43	1	*DEGREASER CLEANER 500ML	Necessary	13.54 FS	*13.54 FS
44	1	*WHEEL BEARING WITH MOUNTI LHS WHEEL BEARING	Necessary	446.08 FS	*446.08 FS
45	1	*WHEEL BEARING HOUSING	Bent	508.11 FS	*508.11 FS
46	1	*OVAL HEXAGON SOCKET HEAD	Necessary	6.23 FS	*6.23 FS
47	1	*SHOULDERED HEX NUT SELF	Necessary	2.59 FS	*2.59 FS
48	1	*GUIDE JOINT	Necessary	109.87 FS	*109.87 FS
49	1	*SHOULDERED HEX NUT (3 PCS)	Necessary	6.74 FS	*6.74 FS
50	1	*SHOULDERED HEX NUT	Necessary	4.27 FS	*4.27 FS
51	1	*BRACKET LHS LOWER ARM MTG	Bent	132.18 FS	*132.18 FS
52	1	*BOLT HEX HD WITH SHOULD	Necessary	8.60 FS	*8.60 FS
53	1	*HEXAGON FLANGE SCREW	Necessary	7.27 FS	*7.27 FS
54	1	*BOLT HEX HD WITH SHOULD (2 PCS)	Necessary	8.67 FS	*8.67 FS
55	1	*DEGREASER CLEANER 500ML	Necessary	13.54 FS	*13.54 FS
56	1	*GAS -FILLED SHOCK ABSORBER (FRONT LH)	Bent	312.32 FS	*312.32 FS
57	1	*BALL BEARING (FRONT LH)	Necessary	26.40 FS	*26.40 FS
58	1	*SHOULDERED HEX NUT (FRONT LH)	Necessary	4.33 FS	*4.33 FS
59	1	*BOLT HEX HD (FRONT LH) (3 PCS)	Necessary	10.91 FS	*10.91 FS
60	1	*OVAL HEXAGON SOCKET HEAD (FRONT LH)	Necessary	6.23 FS	*6.23 FS
61	1	*SHOULDERED HEX NUT SELF (FRONT LH)	Necessary	2.59 FS	*2.59 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	11,644.17	11,488.50
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING ASSISTANCE -AWP	New	195.00	195.00
2	LABOUR	New	3,360.00	2,240.00
3	SPRAY PAINT	New	4,240.00	2,650.00
4	TRANSFER DOOR MECHANISM	New	560.00	280.00
5	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	200.00	200.00
6	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
7	TO ALING LED HEADLIGHT	New	100.00	100.00
8	R&R RHS U/CARRIAGE	New	1,680.00	840.00
9	R&R LHS U/CARRIAGE	New	1,120.00	840.00
10	B&P WHEEL ALIGNMENT	New	300.00	300.00
Gross Labour Cost (\$\$)			12,115.00	8,005.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >