



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2796Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<b><u>REPLACEMENT OF PARTS</u></b>	DISTORTED		
	FRT DOOR MIRROR LH		670.00	670.00
	LESS 20% DISCOUNT		-134.00	-134.00
			536.00	536.00
	<b><u>LABOUR</u></b>	NOT NECESSARY		
	PANEL BEATING.		200.00	150.00
	SPRAY PAINTING CHARGE.		150.00	100.00
	CHECK WIRING AND LIGHTING.		30.00	-
			380.00	250.00
<b>GRAND TOTAL</b>			<b>916.00</b>	<b>786.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>650.00</b>

Report Ref No. NS/INC22007443/Gncm4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.