

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22007444/EVY3Q2  
**Date:** 25/10/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00009352200
Claimant Vehicle No :	SLR8080D	Insured Vehicle No :	PA8680P
Date of Loss:	02/08/2022	Nature of Claim:	TP
		Claim No:	SNM22D205402/C02/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR8080D	Engine No:	37345458B38A15A
Make & Model:	BMW X1, 1.5 SDRIVE 18I (A)	Chassis No:	WBAJG120503G76722
Reg. Date:	30/11/2018 (Man. Year: 2018)	Odometer:	42318 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,676.35	2,492.90	4,183.45	62.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,022.00	5,128.00	2,894.00	36.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>14,698.35</b>	<b>7,620.90</b>	<b>7,077.45</b>	<b>48.15</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,028.88</b>	<b>533.46</b>	<b>495.42</b>	<b>48.15</b>
<b>Nett Amount (S\$)</b>	<b>15,727.23</b>	<b>8,154.36</b>	<b>7,572.87</b>	<b>48.15</b>

### INSPECTION

Date of Assignment:	04/08/2022		
Date Inspected:	30/08/2022 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941	
Estimated Period of Repair:	5.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2022)
<b>Parts:</b>	M1-SUV	BMW X1 1.5 SDRIVE 18I (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLR8080D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*BOOTLID	Dented	1,298.95 FS	*1,298.95 FS
3	1		*REAR LH BUMPER MOUNT	Not Necessary	166.90 FS	*- FS
4	1		*REAR RH BUMPER MOUNT	Not Necessary	166.90 FS	*- FS
5	1		*RR BUMPER CARRIER	Not Necessary	523.75 FS	*- FS
6	1		*REAR BUMPER TRIM PANEL BOTTOM (BASI)	Cut	208.45 FS	*208.45 FS
7	1		*MOUNTING SMART OPENER	Not Necessary	47.00 FS	*- FS
8	1		*RR BUMPER LH CORNER MOUNTING	Not Necessary	147.50 FS	*- FS
9	1		*RR BUMPER RH CORNER MOUNTING	Not Necessary	147.50 FS	*- FS
10	1		*REAR BUMPER PANEL PRIMED	Repair	907.80 FS	*- FS
11	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Cut	266.90 FS	*266.90 FS
12	1		*EMBLEM GROMMET (4 PCS)	Necessary (2 PCS ONLY)	3.80 FS	*1.90 FS
13	1		*BMW PLAQUE WITH ADHESIVE FILM	Necessary	72.85 FS	*72.85 FS
14	1		*LETTERING S DRIVE 18I	Necessary	98.35 FS	*98.35 FS
15	1		*LETTERING X1	Necessary	65.60 FS	*65.60 FS
16	1		*REAR WINDOW (ESG)	Not Necessary	815.55 FS	*- FS
17	1		*BOOTLID SEALING	Not Necessary	169.85 FS	*- FS
18	1		*REAR RH LIGHT IN TRUNK LID	Not Necessary	277.10 FS	*- FS
19	1		*REAR LH LIGHT IN THE SIDE PANEL	Not Necessary	405.85 FS	*- FS
20	1		*REAR RH LIGHT IN THE SIDE PANEL	Not Necessary	405.85 FS	*- FS
21	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
22	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
23	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
24	4		*BLIND RIVET NUT M6	Necessary	10.80 FS	*10.80 FS
25	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **6,676.35**      **2,492.90**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER AND TAILGATE	New	3,400.00	1,700.00
2	TO RESPRAY REAR BUMPER AND TAILGATE	New	2,076.00	1,972.00
3	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
4	TO REPLACE TAIL LIGHT	New	481.00	0.00
5	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECK ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	504.00
6	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	545.00
7	TO CONDUCT WATER LEAK TESTS	New	75.00	71.00
8	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
9	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,022.00</b>	<b>5,128.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >