

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III22007447/UYA3Q2**Date:** 18/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_02  
**Claimant Vehicle No :** YP5242E **Insured Vehicle No :** GBL1584M  
 Date of Loss: 28/07/2022 Nature of Claim: TP Claim No: MFL2022D0004063

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP5242E**  
 Make & Model: ISUZU NQR75UL5A, 5.2 D (M) Engine No: 4HK1551942  
 Reg. Date: 05/01/2017 (Man. Year: 2016) Chassis No: JAAN1R75LG7102424  
 Colour: White Odometer: 215703 km  
 Engine Capacity: 5193 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/75 R17.50 Rear Tyre Size: 215/75 R17.50  
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,973.00	5,220.10	2,752.90	34.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,470.00	870.00	37.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,313.00</b>	<b>6,690.10</b>	<b>3,622.90</b>	<b>35.13</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,300.00</b>		
<b>Nett Amount (\$\$)</b>	<b>10,313.00</b>	<b>5,300.00</b>	<b>5,013.00</b>	<b>48.61</b>
<b>+ Loss of Use (5.0 x S\$120.00/day) (\$\$)</b>		600.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>5,907.45</b>		

INSPECTION

Date of Assignment: 04/08/2022  
 Date Inspected: 04/08/2022 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)  
 BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT  
 Singapore 417883  
 Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA**Manager:** Ezlyna

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Oct 2022)	
Parts:	N/A	ISUZU NQR75UL5A 5.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP5242E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent / Warped	1,355.00 F	*1,355.00 FL
2	2		*FRONT RH DOOR HINGE	Repair	210.00 F	*- FL
3	1		*FRONT RH DOOR SIGNAL LAMP	Broken	162.00 F	*162.00 FL
4	1		*FRONT RH STEP PANEL	Grazed	302.00 F	*302.00 FL
5	1		*FRONT RH CORNER PANEL	Broken	455.00 F	*455.00 FL
6	4		*FRONT RH CORNER PANEL BRACKET	No such part	240.00 F	*- FL
7	1		*FRONT RH MIRROR ARM	Bent	505.00 F	*505.00 FL
8	1		*FRONT RH SIDE MIRROR	Broken	118.00 F	*118.00 FL
9	1		*FRONT RH MIRROR ARM COVER ROUND	Not Necessary	90.00 F	*- FL
10	1		*FRONT RH CORNER PANEL COVER TOP	Not Necessary	62.00 F	*- FL
11	1		*FRONT RH HEAD LAMP	Cracked	480.00 F	*480.00 FL
12	1		*FRONT RH SIGNAL LAMP	Broken	245.00 F	*245.00 FL
13	1		*FRONT RH GRILLE	Cracked	600.00 F	*600.00 FL
14	1		*FRONT RH BUMPER	Distorted	1,100.00 F	*1,100.00 FL
15	1		*FRONT RH BUMPER BRACKET	Distorted	282.00 F	*282.00 FL
16	1		*FRONT RH FOG LAMP	Cracked	302.00 F	*302.00 FL
17	1		*FRONT RH PANEL	Repair	985.00 F	*- FL
18	1		*FRONT RH CORPORATE ADVERTISEMENT & ARTWORK	Necessary	480.00 FS	*200.00 FS
					Sub Total (\$\$)	7,973.00 6,106.00
					- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00 885.90
					Total Parts (\$\$)	7,973.00 5,220.10

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REPLACE AND TRANSFER DOOR PANEL ,FITTING AND MECHANISMS	New	100.00	60.00
2	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	60.00	20.00
3	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	1,200.00	550.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	900.00	800.00
5	TO APPLY RUST PROOFING RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,340.00</b>	<b>1,470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >