

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007448/UEA3Q2**Date:** 17/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220057420
Claimant Vehicle No :	FBK2812D	Insured Vehicle No :	GBD912Z
Date of Loss:	22/07/2022	Nature of Claim:	TP
		Claim No:	1576821633SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK2812D	Engine No:	NC42E1203263
Make & Model:	HONDA CB400SF, 399cc	Chassis No:	NC421603261
Reg. Date:	05/06/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/60Z R17	Rear Tyre Size:	160/60Z R17
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Metzeler 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,915.00	11,396.80	3,518.20	23.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,079.00	515.00	1,564.00	75.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,994.00	11,911.80	5,082.20	29.91
Approved Total (Overridden) (S\$)		9,000.00		
(S\$)	16,994.00	9,000.00	7,994.00	47.04
+ GST 7.00/7.00% (S\$)	1,189.58	630.00	559.58	47.04
Nett Amount (S\$)	18,183.58	9,630.00	8,553.58	47.04
+ Loss of Use (4.0 x S\$20.00/day) (S\$)		80.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,712.00		

INSPECTION

Date of Assignment:	04/08/2022		
Date Inspected:	04/08/2022	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALIGNMENT BODY	Not Necessary	500.00 F	*- FL
2	1		*SET BALANCER HANDLE (CHROME)	Scratched	84.00 F	*84.00 FL
3	1		*BRACKET UNDER FORK	Bent	490.00 F	*490.00 FL
4	1		*CALIPER BRAKE FRONT RH	Repair	513.00 F	*- FL
5	1		*CASE HEADLAMP	Broken	224.00 F	*224.00 FL
6	1		*COOLANT (BMW)	Not Necessary	35.00 F	*- FL
7	1		*COVER STARTER	Not Necessary	202.00 F	*- FL
8	1		*CROWN HANDLE	Cracked	343.00 F	*343.00 FL
9	1		*ECU UNIT	Damaged	1,594.00 F	*1,594.00 FL
10	1		*FOOTREST FRONT LH	Cut	54.00 F	*54.00 FL
11	1		*FOOTREST REAR LH	Cut	56.00 F	*56.00 FL
12	1		*FORK FRONT ASSY LH	Bent	1,358.00 F	*1,358.00 FL
13	1		*FORK FRONT ASSY RH	Bent	1,358.00 F	*1,358.00 FL
14	1		*FUEL TANK ASSY (RED)	Dented	1,443.00 F	*1,443.00 FL
15	1		*GASKET COVER COIL PULSER	Not Necessary	13.00 F	*- FL
16	1		*GASKET FUEL PUMP	Necessary	35.00 F	*35.00 FL
17	1		*GRIP HANDLE (PLAYLIFE)	Twisted	42.00 F	*42.00 FL
18	1		*GRIP TANK (AFTERMARKET)	Torn	52.00 F	*52.00 FL
19	1		*GUARD ENGINE BLACK -3 POINTS	Bent	196.00 F	*196.00 FL
20	1		*HANDLE BAR	Bent	181.00 F	*181.00 FL
21	1		*HEADLAMP ASSY	Broken	427.00 F	*427.00 FL
22	1		*LEVER BRAKE	Scratched	54.00 F	*54.00 FL
23	1		*LEVER CLUTCH	Scratched	28.00 F	*28.00 FL
24	1		*MIRROR AFTER MARKET	Broken	91.00 F	*91.00 FL
25	1		*MUDGUARD FRONT RED	Broken	203.00 F	*203.00 FL
26	1		*0.5 PCS OIL BRAKE (KUTTEN KEULER) DOT 4	Necessary	8.00 F	*8.00 FL
27	1		*PEDAL GEAR	Bent	125.00 F	*125.00 FL
28	1		*PLATE HEADLAMP LH	Bent	52.00 F	*52.00 FL
29	1		*PLATE HEADLAMP RH	Bent	52.00 F	*52.00 FL
30	1		*RADIATOR ASSY	Not Necessary	980.00 F	*- FL
31	1		*RECEIVER UNIT	Damaged	224.00 F	*224.00 FL
32	1		*RUBBER GEAR PEDAL	Necessary	6.00 F	*6.00 FL
33	1		*SEAL DUST STEERING CONE 1	Necessary	18.00 F	*18.00 FL
34	1		*SIGNAL FRONT RH ASSY	Broken	154.00 F	*154.00 FL
35	1		*SIGNAL FRONT LH ASSY	Cracked	154.00 F	*154.00 FL
36	1		*SPEEDOMETER ASSY	Cracked	1,680.00 F	*1,680.00 FL
37	1		*STAY FRONT COWLING	Bent	133.00 F	*133.00 FL
38	1		*PLATE NUMBER FRONT (WHITE) STRAIGHT	Bent	20.00 FS	*10.00 FS
39	1		*SET STEERING CONE UPPER	Necessary	42.00 F	*42.00 FL
40	1		*SWITCH IGNITION	Damaged	329.00 F	*329.00 FL
41	2		*TAPE CRASH BAR BLACK CARBON	Necessary	32.00 F	*32.00 FL
42	1		*WIRE HARNESS ASSY	Cracked / Damaged	1,330.00 F	*1,330.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,915.00	12,662.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	1,265.20
Total Parts (\$)	14,915.00	11,396.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A	New	63.00	35.00
2	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	2,016.00	480.00
Gross Labour Cost (S\$)			2,079.00	515.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >