

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007449/GNY3E2**Date:** 07/06/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00005122205

**Claimant Vehicle
No :** BICYCLE**Insured Vehicle
No :** SKZ741C

Date of Loss: 29/01/2022

Nature of Claim: TP

Claim
No: SNM22D200831/C02/TANKLDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **BICYCLE**

Make & Model: ELECTRIC BICYCLE SUV-7, (A)

Engine No: HIDDEN

Reg. Date: (Man. Year:)

Chassis No: HIDDEN

Colour: Others

Odometer: 0 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

Rear Tyre Size:

Front Left Side: Roval CL 50 0 mm

Rear Left Side: Roval CL 50 0 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,985.00	10,985.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	10,985.00	10,985.00	0.00	0.00

INSPECTION

Date of Assignment: 20/10/2022

Date Inspected: 05/08/2022 Inspected At:

Blk 41 Simei Rise #05-21 Savannah CondoPark

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jun 2023)	
Parts:	N/A	ELECTRIC BICYCLE SUV-7 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for BICYCLE)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRAMESET (INCLUDING FORK, HEADSET AND SEATPOST)	Damaged	5,000.00 F	*5,000.00 F
2	1		*WHEELS	Damaged	2,500.00 F	*2,500.00 F
3	1		*GROUP SET (MECHANICAL PARTS)	Damaged	2,800.00 F	*2,800.00 F
4	1		*SADDLE (SEAT)	Damaged	195.00 F	*195.00 F
5	1		*PEDAL	Damaged	150.00 F	*150.00 F
6	1		*STEM	Damaged	180.00 F	*180.00 F
7	1		*TIRES	Damaged	160.00 F	*160.00 F
Total Parts (S\$)						10,985.00
						10,985.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >