



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 323Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT HEADLAMP ASSY (CONSISTENT)	CUT	5,974.00	5,947.00
1	FRONT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	1,298.00	-
1	FRONT BUMPER ASSY (CONSISTENT)	BUCKLED	1,670.00	1,670.00
1	FRONT AIRMATIC(RIGHT HAND) ABSORBER (CONSISTENT)	BENT/PUNCTURE	2,230.00	2,230.00
	LESS 10% DISCOUNT		-1,117.20	-984.70
			10,054.80	8,862.30
	<b><u>LABOUR</u></b>			
	TO RENEW UNDERCARRIAGE PARTS.		200.00	150.00
	TO ERASE AND PERFORM SUSPENSION HEIGHT SETTING.		80.00	60.00
	TO RESPRAY ALL AFFECTED PARTS.		600.00	440.00
	TO RENEW ABOVE BODY PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER.		700.00	400.00
	WHEEL ALIGNMENT.		60.00	60.00
			1,640.00	1,110.00
<b>GRAND TOTAL</b>			<b>11,694.80</b>	<b>9,972.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>7,950.00</b>

Report Ref No. CS/ASM22007450/Kcy3m4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.