

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS22007460/KQY3Q2**Date:** 20/10/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** GBL517P **Insured Vehicle No :** SGX1388R

Date of Loss: 13/07/2022 Nature of Claim: TP Claim No: DMPC2200294H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL517P**

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KDB068944

Reg. Date: 26/02/2021 (Man. Year: 2020) Chassis No: JTFAT35Y60K216278

Colour: Silver Odometer: 18927 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 155 R12X8 (D)

Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9/9 mm

Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9/9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	68.75	68.75	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	520.00	260.00	260.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>588.75</b>	<b>328.75</b>	<b>260.00</b>	<b>44.16</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>41.21</b>	<b>23.01</b>	<b>18.20</b>	<b>44.16</b>
<b>Nett Amount (\$\$)</b>	<b>629.96</b>	<b>351.76</b>	<b>278.20</b>	<b>44.16</b>

INSPECTION

Date of Assignment: 04/08/2022

Date Inspected: 05/08/2022 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)  
160 Sin Ming Drive #04-01, Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 19 Oct 2022)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBL517P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DYNA STICKER	Necessary	45.00 FL	*45.00 FL
2	1		*REAR NUMBER PLATE	Bent	25.00 FS	*25.00 FS
3	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					<b>Sub Total (\$\$)</b>	<b>80.00</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>11.25</b>
					<b>Total Parts (\$\$)</b>	<b>68.75</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE COMPANY LOGO LETTERING DECAL	New	220.00	0.00
2	TO SPRAY PAINT ON REAR TAILGATE AND REAR FLOOR END PANEL	New	300.00	260.00
<b>Gross Labour Cost (\$\$)</b>			<b>520.00</b>	<b>260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >