

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007466/APA3Q2**Date:** 19/01/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900230985
Claimant Vehicle No :	GBF9253Y	Insured Vehicle No :	GBG8425U
Date of Loss:	29/07/2022	Nature of Claim:	TP
		Claim No:	0858878184SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF9253Y	Engine No:	1KD2597994
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Chassis No:	KDY2318025002
Reg. Date:	17/04/2017 (Man. Year: 2016)	Odometer:	110406 km
Colour:	Green		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R13C
Front Left Side:	Arivo 6 mm	Rear Left Side:	Arivo 6 mm
Front Right Side:	Arivo 6 mm	Rear Right Side:	Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,982.57	10,598.92	16,383.65	60.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,330.00	4,140.00	7,190.00	63.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,312.57	14,738.92	23,573.65	61.53
Approved Total (Overridden) (S\$)		11,800.00		
Nett Amount (S\$)	38,312.57	11,800.00	26,512.57	69.20
+ Loss of Use (15.0 x S\$100.00/day) (S\$)		1,500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		13,307.45		

INSPECTION

Date of Assignment:	02/08/2022	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	02/08/2022 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	13.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	727.10 FL	*727.10 FL
2	2		*FRONT BUMPER BRACKET	Bent	425.40 FL	*425.40 FL
3	2		*FRONT BUMPER FOGLAMP	Not Necessary	391.20 FL	*- FL
4	2		*HEAD LAMP	Cracked	1,994.60 FL	*1,994.60 FL
5	2		*HEAD LAMP LOWER RUBBER	Not Necessary	94.40 FL	*- FL
6	1		*FRONT CHASSIS CROSS MEMBER	Repair	958.00 FL	*- FL
7	1		*FRONT GRILLE	Cracked	479.80 FL	*479.80 FL
8	1		*FRONT GRILLE LOGO	Necessary	78.00 FL	*78.00 FL
9	1		*FRONT PANEL	Dented	1,156.70 FL	*1,156.70 FL
10	1		*FRONT WIPER PANEL	Not Necessary	349.60 FL	*- FL
11	1		*FRONT SIDE MIRROR (ROUND) LH	Not Necessary	246.80 FL	*- FL
12	1		*FRONT SIDE MIRROR STAND LH	Not Necessary	669.00 FL	*- FL
13	1		*FRONT WINDSCREEN RUBBER	Necessary	365.00 FL	*365.00 FL
14	1		*FRONT CABIN HINGE	Not Necessary	3,270.00 FL	*- FL
15	1		*FRONT APRON GARNISH (CENTER)	Deformed	296.70 FL	*296.70 FL
16	2		*FRONT CORNER PANEL LOWER APRON GARNISH	Not Necessary	229.80 FL	*- FL
17	2		*FRONT CORNER PANEL (LOWER)	Not Necessary	495.40 FL	*- FL
18	4		*FRONT BRAKE PIPE	Not Necessary	1,292.00 FL	*- FL
19	1		*AIR CON BLOWER MOTOR	Cracked	1,394.00 FL	*1,394.00 FL
20	1		*AIR CON COOLING COIL	Cracked	2,439.00 FL	*1,782.00 FL
21	2		*AIR CON PIPE	Not Necessary	950.00 FL	*- FL
22	2		*AIR CON HOSE	Not Necessary	776.00 FL	*- FL
23	1		*TAILGATE	Dented	1,370.00 FL	*1,370.00 FL
24	4		*TAILGATE HINGE	Bent (2 PCS ONLY)	660.00 FL	*330.00 FL
25	1		*TAILGATE SIDE LOCK	N/S Dented	250.00 FL	*125.00 FL
26	1		*TAILGATE STOPPER RUBBER	N/S Missing	70.00 FL	*35.00 FL
27	2		*TAILGATE STOPPER BRACKET	Not Necessary	350.00 FL	*- FL
28	1		*TAILGATE STICKER TOYOTA	Necessary	167.60 FL	*167.60 FL
29	1		*TAILGATE STICKER CHINESE WORDS	Necessary	50.00 FL	*30.00 FL
30	2		*SIDE GATE	Repair	3,937.80 FL	*- FL
31	2		*SIDE GATE SAFETY LOCK	Not Necessary	264.20 FL	*- FL
32	2		*TAIL LAMP	Cracked	490.00 FL	*490.00 FL
33	1		*TAIL LAMP SUPPORT BRACKET	N/S Bent	370.00 FL	*185.00 FL
34	2		*TAIL LAMP LOWER REFLECTOR	Not Necessary	172.00 FL	*- FL
35	1		*REAR STICKER DYNA	Necessary	45.00 FL	*45.00 FL
36	1		*REAR END PANEL	Dented	1,245.00 FL	*495.00 FL
37	2		*REAR END PANEL REFLECTOR	Not Necessary	130.00 FL	*- FL
38	2		*REAR END PANEL STICKER (BLACK)	Necessary	100.00 FL	*20.00 FL
39	1		*REAR STORAGE BOX	Not Necessary	200.00 FL	*- FL
40	1		*FRONT NUMBER PLATE	Deformed	50.00 FS	*50.00 FS
41	1		*SET FRONT GRILLE CLIP	Necessary	40.00 FS	*20.00 FS
42	1		*FRONT PANEL SEALANT	Necessary	150.00 FS	*60.00 FS
43	1		*SET DASHBOARD CLIP	Not Necessary	150.00 FS	*- FS
44	1		*SET DASHBOARD CENTER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
45	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
46	1		*FRONT WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*30.00 FS
47	1		*REAR NUMBER PLATE	Damaged	50.00 FS	*50.00 FS
48	1		*TAIL GATE 70KM/H STICKER	Necessary	40.00 FS	*15.00 FS
49	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*40.00 FS
50	1		*REAR STEP BRACKET	Not Necessary	80.00 FS	*- FS
51	1		*REAR FLOOR TOP ALUMINIUM PANEL (SPECIAL TYPE)	Buckled	3,800.00 FS	*800.00 FS
52	1		*REAR REVERSE CAMERA	Damaged	350.00 FS	*300.00 FS
53	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 34,220.10 13,596.90

Report was unsubmitted during this print-out.

1/19/23, 11:44 AM				Adjuster Report		
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					7,237.53	2,997.98
Total Parts (S\$)					26,982.57	10,598.92
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD ,CUT ,ADJUST KNOCK	New	2,000.00	900.00
2	TO PUTTY SPRAY PAINT ,POLISH WAX	New	1,200.00	900.00
3	TO SPRAY TUFF COAT	New	250.00	60.00
4	WIRING BULB CHECKING	New	80.00	30.00
5	CONDUCT WATER TER LEAKAGE TEST	New	80.00	0.00
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
7	REFOCUS HEADLAMP BEAM	New	60.00	0.00
8	REMOVE AND REFIX AIRCON BLOWER COOLING COIL ,AIR CON CONDENSER AND REFILL AIRCON GAS	New	250.00	200.00
9	REMOVE AND REINSTALL DASHBOARD	New	650.00	220.00
10	REMOVE AND REFIX FRONT WINDSCREEN	New	120.00	120.00
11	REMOVE AND REFIX FRONT VIDEO RECORDER	New	80.00	50.00
12	RESET RADIO SYSTEM	New	200.00	0.00
13	LIFT UP CABIN	New	1,800.00	0.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
15	TO PANEL BEAT ,WELD ,CUT ,ADJUST KNOCK	New	1,400.00	700.00
16	TO PUTTY ,SPRAY PAINT ,POLISH WAX	New	1,400.00	550.00
17	REMOVE AND REFIX REAR RAILING	New	350.00	150.00
18	REMOVE AND REFIX REVERSE SENSOR	New	80.00	50.00
19	REMOVE AND REFIX REAR FLOOR AUMINIUM	New	650.00	150.00
20	REAR CHASSIS ALIGHMENT	New	250.00	0.00
Gross Labour Cost (S\$)			11,330.00	4,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >