

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007471/TVY3E2**Date:** 04/01/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00129762202
Claimant Vehicle No :	SMJ7590K	Insured Vehicle No :	SKH801H
Date of Loss:	03/08/2022	Nature of Claim:	TP
		Claim No:	SNM22D205458/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ7590K	Engine No:	G4FGKU109567
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHD841CMKU879134
Reg. Date:	20/03/2019 (Man. Year: 2019)	Odometer:	53856 km
Colour:	Dark Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,483.00	3,588.32	5,894.68	62.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,550.00	1,980.00	56.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,013.00	5,138.32	7,874.68	60.51
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	13,013.00	3,850.00	9,163.00	70.41
+ GST 7.00/7.00% (S\$)	910.91	269.50	641.41	70.41
Nett Amount (S\$)	13,923.91	4,119.50	9,804.41	70.41

INSPECTION

Date of Assignment:	10/08/2022	
Date Inspected:	05/08/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2023)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ7590K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,782.40 FL	*1,782.40 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	34.90 FL	*34.90 FL
3	1		*BOOTLID AVANTE EMBLEM	Necessary	45.90 FL	*45.90 FL
4	1		*BOOTLID REVERSE CAMERA	Not Necessary	826.10 FL	*- FL
5	1		*BOOTLID LOCK	Not Necessary	125.30 FL	*- FL
6	1		*BOOTLID RH HINGE	Not Necessary	94.30 FL	*- FL
7	1		*BOOTLID LH HINGE	Not Necessary	94.30 FL	*- FL
8	1		*BOOTLID WEATHERSTRIP	Not Necessary	109.10 FL	*- FL
9	1		*BOOTLID RH LAMP	Not Necessary	664.10 FL	*- FL
10	1		*BOOTLID LH LAMP	Not Necessary	664.10 FL	*- FL
11	1		*REAR BUMPER	Deformed	459.80 FL	*459.80 FL
12	1		*REAR BUMPER LOWER GARNISH	Deformed	353.20 FL	*340.60 FL
13	1		*REAR BUMPER NUMBER PLATE GARNISH	Deformed	29.90 FL	*29.90 FL
14	1		*REAR BUMPER LH NUMBER PLATE LAMP	Cracked	28.30 FL	*28.30 FL
15	1		*REAR BUMPER RH NUMBER PLATE LAMP	Cracked	28.30 FL	*28.30 FL
16	1		*REAR BUMPER RH SIDE LAMP	Not Necessary	201.50 FL	*- FL
17	1		*REAR BUMPER LH SIDE LAMP	Not Necessary	201.50 FL	*- FL
18	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	33.10 FL	*- FL
19	1		*REAR BUMPER LH SIDE RETAINER	Cracked	33.10 FL	*33.10 FL
20	1		*REAR BUMPER REINFORCEMENT	Cracked	302.10 FL	*294.80 FL
21	1		*REAR BUMPER REINFORCEMENT RH BRACKET	Not Necessary	78.60 FL	*- FL
22	1		*REAR BUMPER REINFORCEMENT LH BRACKET	Not Necessary	78.60 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT RH UPPER BRACKET	Not Necessary	12.00 FL	*- FL
24	1		*REAR BUMPER REINFORCEMENT LH UPPER BRACKET	Not Necessary	12.00 FL	*- FL
25	1		*REAR BUMPER REINFORCEMENT RH LOWER BRACKET	Cracked	12.00 FL	*12.00 FL
26	1		*REAR BUMPER REINFORCEMENT LH LOWER BRACKET	Cracked	12.00 FL	*12.00 FL
27	1		*RH TAILLAMP	Not Necessary	1,052.10 FL	*- FL
28	1		*LH TAILLAMP	Cracked	1,052.10 FL	*1,052.10 FL
29	1		*END PANEL	Repair	478.00 FL	*- FL
30	1		*END PANEL INNER GARNISH	Deformed	59.80 FL	*59.80 FL
31	1		*REAR ANTENNA SENSOR	Not Necessary	55.00 FL	*- FL
32	1		*REAR RH FENDER INNER TRIM	Not Necessary	209.00 FL	*- FL
33	1		*REAR LH FENDER INNER TRIM	Torn	209.00 FL	*209.00 FL
34	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	640.80 FL	*- FL
35	1		*EXHAUST SILENCER	Not Necessary	793.20 FL	*- FL
36	1		*EXHAUST SILENCER GASKET	Not Necessary	32.00 FL	*- FL
37	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
38	1		*BOOTLID SEALANT	Not Necessary	100.00 FS	*- FS
39	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
40	1		*SET REAR BUMPER LOWER GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
41	1		*SET END PANEL INNER GARNISH CLIPS	Not Necessary	45.00 FS	*- FS
42	1		*END PANEL JOINT SEALANT	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SET REAR RH FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
44	1		*SET REAR LH FENDER INNER TRIM CLIPS	Necessary	80.00 FS	*20.00 FS
45	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
46	1		*REAR NUMBER PLATE FRAME	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,662.50	4,472.90
- List Item Discount on L Items 20.00/20.00% (\$)	2,179.50	884.58
Total Parts (\$)	9,483.00	3,588.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,400.00	700.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	100.00	30.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO CARRY REPAIR	New	100.00	30.00
6	REMOVE AND REPLACE REAR INNER TRIMS, GARNISH AND BOARDS TO CARRY REPAIR	New	320.00	60.00
7	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO CARRY REPAIR	New	180.00	0.00
8	REMOVE AND REPLACE BOOTLID REVERSE CAMERA TO CARRY REPAIR	New	150.00	0.00
Gross Labour Cost (\$\$)			3,530.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >