

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22007477/UPA3Q2**Date:** 05/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800072787
<b>Claimant Vehicle No :</b>	FBQ3983E	<b>Insured Vehicle No :</b>	SMA8159P
Date of Loss:	08/06/2022	Nature of Claim:	TP
		Claim No:	1668060944SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FBQ3983E</b>	Engine No:	SJ301000117
Make & Model:	KYMCO SUPER JOCKEY 150I, 149cc	Chassis No:	RFBSJ30GAK1000139
Reg. Date:	24/09/2019 (Man. Year: 2019)	Odometer:	18069 km
Colour:	White		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	3.50-10	Rear Tyre Size:	130-70-10
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	666.00	444.70	221.30	33.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	631.00	510.00	121.00	19.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,297.00</b>	<b>954.70</b>	<b>342.30</b>	<b>26.39</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>750.00</b>		
<b>(S\$)</b>	1,297.00	750.00	547.00	42.17
<b>+ GST 7.00/7.00% (S\$)</b>	90.79	52.50	38.29	42.17
<b>Nett Amount (S\$)</b>	<b>1,387.79</b>	<b>802.50</b>	<b>585.29</b>	<b>42.17</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment:	05/08/2022		
Date Inspected:	05/08/2022	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER LH BODY (CUT)	Not Consistent With The Impact	108.00 F	*- FL
2	1		*COVER RH B BODY	Cut	41.00 F	*41.00 FL
3	1		*COVER RH SIDE	Cut	19.00 F	*19.00 FL
4	1		*COVER SIDE LOWER RH	Cut	59.00 F	*59.00 FL
5	1		*GRIP HANDLE RH	Cut	13.00 F	*13.00 FL
6	1		*LEVER BRAKE LH (Scratched)	Not Consistent With The Impact	13.00 F	*- FL
7	1		*LEVER BRAKE RH	Scratched	17.00 F	*17.00 FL
8	1		*METER IU (12V) NEW MODEL	Torn	200.00 FS	*165.00 FS
9	1		*MIRROR LH ASSY (Cut)	Not Consistent With The Impact	42.00 F	*- FL
10	1		*MIRROR RH ASSY	Broken	42.00 F	*42.00 FL
11	1		*PROTECTOR MUFFLER	Cut	42.00 F	*42.00 FL
12	1		*STICKER (SINGAPORE POST) BOX REAR	Necessary	70.00 FS	*70.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	666.00	468.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	23.30
Total Parts (\$\$)	666.00	444.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINT ON REAR FIBRE BOX	New	260.00	260.00
2	TRANSPORT CHARGES	New	56.00	0.00
3	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	315.00	250.00
<b>Gross Labour Cost (\$)</b>			<b>631.00</b>	<b>510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >