



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 3944S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER, REAR BUMPER	BUCKLED	485.60	485.60
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	* CHECK	332.70	-
1	COVER, REAR BUMPER, LOWER	SERVICEABLE	22.00	-
1	GUARD, REAR BUMPER, CENTER	DENTED / CUT	374.50	374.50
1	RETAINER, REAR BUMPER SIDE, RH	SERVICEABLE	132.60	-
1	REFLECTOR ASSY, REFLEX, RH	SERVICEABLE	39.00	-
1	COVER, DECK TRIM, REAR	SERVICEABLE	126.70	-
1	PANEL SUB-ASSY, BODY LOWER BACK	TO REPAIR SEE LABOUR	651.00	-
	LESS 25% DISCOUNT		-541.03	-215.03
			1,623.07	645.07
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	95.00	60.00
1	REAR SPOILER CLIP (SN)	NOT NECESSARY	70.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	180.00	-
1	SET REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	85.00	-
1	END PANEL TRIM CLIP (SN)	NOT NECESSARY	65.00	-
			1,195.00	60.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, BODY LOWER BACK.		2,200.00	200.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT ELECTRICAL WIRING, BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	480.00	-

Report Ref No. CS/AGI22007479/Kcy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	250.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,200.00	220.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS.	NOT NECESSARY	380.00	-
			7,390.00	470.00
GRAND TOTAL			10,208.07	1,175.07
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$249.53 NETT)				1,175.07

Report Ref No. CS/AGI22007479/Kcy3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.