

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22007483/RNY3Q2**Date:** 30/11/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00051242203

**Claimant Vehicle  
No :** PC6527C**Insured  
Vehicle No :** GBE9499K

Date of Loss: 03/08/2022

Nature of Claim: TP

Claim  
No: SNM22D205459/C02/TANKW**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **PC6527C**

Make &amp; Model: TOYOTA HIACE, 3.0 COMMUTER GL (A)

Engine No: 1KD2744852

Reg. Date: 25/10/2017 (Man. Year: 2017)

Chassis No: KDH2230033815

Colour: White

Odometer: 13996 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15C

Rear Tyre Size:

195 R15C

Front Left Side: Bridgestone 7 mm

Rear Left Side:

Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side:

Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,487.20	5,047.02	4,440.18	46.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,600.00	4,950.00	5,650.00	53.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>20,087.20</b>	<b>9,997.02</b>	<b>10,090.18</b>	<b>50.23</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,406.10</b>	<b>699.79</b>	<b>706.31</b>	<b>50.23</b>
<b>Nett Amount (\$\$)</b>	<b>21,493.30</b>	<b>10,696.81</b>	<b>10,796.49</b>	<b>50.23</b>

**INSPECTION**

Date of Assignment: 05/08/2022

Date Inspected: 11/08/2022

Inspected At:

SC Auto Industries (S) Pte Ltd (HQ)  
51 Senoko Road, #03-01  
Singapore 758133

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$9,997.03

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 30 Nov 2022)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC6527C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,350.00 F	*- FL
2	4		*REAR WINDSCREEN SEALANT	Necessary	200.00 F	*200.00 FL
3	2		*TAILLAMP LH & RH	Not Necessary	720.00 F	*- FL
4	1		*TAILGATE CHROME	Cracked	520.50 F	*520.50 FL
5	1		*REAR PANEL INNER	Bent	1,550.00 F	*1,550.00 FL
6	1		*REAR LOGO	Necessary	115.60 F	*115.60 FL
7	1		*REAR EMBLEM	Necessary	125.60 F	*125.60 FL
8	2		*REAR REVERSE SENSOR	Distorted	771.00 F	*771.00 FL
9	1		*TAILGATE	Bent	3,200.00 F	*3,200.00 FL
10	1		*TAILGATE LOCK	Not Necessary	589.50 F	*- FL
11	1		*REAR NUMBER PLATE WITH PLATE HOLDER	Not Necessary	80.00 F	*- FL
12	1		*INFORMATION STICKER	Necessary	65.00 FS	*65.00 FS
13	1		*SUNDRIES	Necessary	200.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>9,487.20</b>	<b>6,667.70</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	1,620.68
<b>Total Parts (\$\$)</b>	<b>9,487.20</b>	<b>5,047.02</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE ,REINSTALL AND CHECK REAR BUMPER WIRENESS AND RECORDING CAMERA	New	650.00	350.00
2	LABOUR TO REINSTALL REAR WINDSCREEN	New	800.00	300.00
3	LABOUR TO REMOVE ,REPAIR AND REINSTALL REAR BUMPER ,REAR PANEL ,TAILGATE ,FLOOR BOOT	New	5,200.00	2,400.00
4	LABOUR TO RESPRAY REAR PANEL,TAILGATE ,FLOOR BOOT	New	2,600.00	1,500.00
5	LABOUR TO REMOVE & REINSTALL SEAT UPHOLSTERY	New	1,000.00	300.00
6	LABOUR TO CARRY OUT DIAGNOSTIC CHECK	New	350.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>10,600.00</b>	<b>4,950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >