

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007486/ACY3E2**Date:** 21/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00000582200
Claimant Vehicle No :	GBB1844R	Insured Vehicle No :	SMS1781T
Date of Loss:	04/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202331/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB1844R	Engine No:	64698051564127
Make & Model:	MERCEDES-BENZ VITO 111, 2.1 D L (M)	Chassis No:	WDF63960323432158
Reg. Date:	01/09/2008 (Man. Year: 2008)	Odometer:	316300 km
Colour:	Grey		
Engine Capacity:	2148 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R16	Rear Tyre Size:	225/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,871.91	5,701.48	4,170.43	42.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	1,830.00	2,050.00	52.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,751.91	7,531.48	6,220.43	45.23
Approved Total (Overridden) (\$\$)		4,000.00		
Nett Amount (\$\$)	13,751.91	4,000.00	9,751.91	70.91

INSPECTION

Date of Assignment:	17/08/2022	
Date Inspected:	08/08/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Oct 2022)	
Parts:	N/A	MERCEDES-BENZ VITO 111 2.1 D L (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB1844R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	2,423.00 FL	*2,120.00 FL
2	1		*TAILGATE LOGO	Necessary	75.20 FL	*75.20 FL
3	1		*TAILGATE EMBLEM III	Necessary	112.00 FL	*112.00 FL
4	1		*TAILGATE EMBLEM CDI	Necessary	69.20 FL	*69.20 FL
5	1		*TAILGATE LOCK OUTER HANDLE	Damaged	465.10 FL	*302.00 FL
6	1		*TAILGATE STOPPER	Not Necessary	28.00 FL	*- FL
7	1		*TAILGATE INNER TRIM	Torn	271.80 FL	*271.80 FL
8	1		*TAILGATE WEATHERSTRIP	Cut	395.00 FL	*395.00 FL
9	1		*TAILGATE WEATHERSTRIP PROTECTOR	Cracked	485.20 FL	*320.00 FL
10	1		*TAILGATE INNER LOCK	Damaged	475.60 FL	*280.00 FL
11	1		*TAILGATE LOWER LOCK	Not Necessary	45.20 FL	*- FL
12	2		*TAILGATE DAMPER	Not Necessary	254.80 FL	*- FL
13	2		*TAILGATE INNER LOCK HANDLE COVER	Not Necessary	39.20 FL	*- FL
14	1		*TAILGATE KEY LOCK	Not Necessary	294.70 FL	*- FL
15	2		*TAILLAMP LOWER GARNISH	Not Necessary	334.00 FL	*- FL
16	2		*TAILLAMP LOWER GARNISH RETAINER	Not Necessary	130.00 FL	*- FL
17	1		*REAR BUMPER (CENTER)	Distorted	715.00 FL	*715.00 FL
18	1		*REAR BUMPER BASE (CENTER)	Cracked	240.00 FL	*240.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	130.00 FL	*130.00 FL
20	2		*REAR SIDE BUMPER	Deformed	480.00 FL	*480.00 FL
21	2		*REAR BUMPER REFLECTOR	Not Necessary	78.00 FL	*- FL
22	1		*REAR END PANEL (INNER)	Repair	1,043.20 FL	*- FL
23	1		*REAR END PANEL (OUTER)	Dented	597.00 FL	*597.00 FL
24	1		*REAR SPARE TYRE CHAIN BOX	Not Necessary	398.70 FL	*- FL
25	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
26	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
27	1		*SET TAILLAMP LOWER GARNISH CLIP	Not Necessary	40.00 FS	*- FS
28	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
29	1		*SET TAILGATE INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
30	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
31	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
32	1		*TAILGATE STICKER 70KM/H	Necessary	30.00 FS	*15.00 FS
33	1		*REAR END PANEL (INNER) SEALANT	Not Necessary	150.00 FS	*- FS
34	1		*REAR END PANEL (OUTER) SEALANT	Necessary	150.00 FS	*60.00 FS
35	1		*REAR SPARE TYRE	Not Necessary	350.00 FS	*- FS
36	1		*SET TAILGATE CENTER MOULDING (CHROME) CLIP	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,829.90	6,312.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	957.99	610.72
Total Parts (\$\$)	9,871.91	5,701.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND REPLACE PARTS	New	1,600.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	800.00
3	WIRNING, BULB CHECKINNG	New	180.00	30.00
4	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
5	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
6	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
7	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$)			3,880.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >