

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 4895Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE	BENT	1,480.60	1,210.40
2	TAIL GATE DAMPER	SERVICEABLE	403.20	-
1	TAIL GATE LOCK	TO REPAIR SEE LABOUR	361.40	-
1	TAIL GATE REAR W/S MOULDING	NECESSARY	203.00	203.00
1	TAIL GATE LOGO	NECESSARY	56.00	56.00
1	TAIL GATE OUTER HANDLE	SERVICEABLE	295.60	-
1	REAR BUMPER	BENT	731.70	560.30
2	REAR BUMPER REFLECTOR	SERVICEABLE	102.00	-
2	REAR BUMPER RETAINER	N/S DISTORTED	123.60	61.80
1	REAR PANEL	BENT	531.70	531.70
1	REAR PANEL TOP GARNISH	MTG DISTORTED	123.00	123.00
1	REAR BOARD COVER	CRACKED	280.00	280.00
2	TAIL LAMP	N/S CRACKED	905.80	417.90
1	REAR BOX COVER	NO SUCH PARTS	750.00	-
	LESS 25% DISCOUNT		-	-861.03
			6,347.60	2,583.07
	SPECIAL NETT ITEMS			
1	TAIL GATE RUBBER (\$301.40) (50%) (SN)	CUT	361.40	150.70
1	REAR BUMPER SENSOR (SN)	CRACKED	350.00	200.00
1	NUMBER PLATE (SN)	SERVICEABLE	80.00	-
			791.40	350.70
	<u>LABOUR</u>			
	TO REMOVE AND REFIT REAR W/S N CUSHION.		350.00	180.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF TAIL GATE LOCK .		850.00	600.00
	SPRAY PAINTING .		950.00	660.00
			2,150.00	1,440.00
	GRAND TOTAL		9,289.00	4,373.77

Report Ref No. CS/AGI22007488/Kqy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI22007488/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser