

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22007489/KCY3Q2**Date:** 07/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00013442100
Claimant Vehicle No :	SKV3983Y	Insured Vehicle No :	SMD3996G
Date of Loss:	30/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D205453/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV3983Y	Engine No:	CMS041950
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 TSI (A)	Chassis No:	WVWZZZ13ZFBV018632
Reg. Date:	13/08/2015 (Man. Year: 2015)	Odometer:	68865 km
Colour:	Blue		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	235/40Z R18
Front Left Side:	Lanvigaton 9 mm	Rear Left Side:	Lanvigaton 9 mm
Front Right Side:	Lanvigaton 9 mm	Rear Right Side:	Lanvigaton 9 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,022.20	2,490.30	531.90	17.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	440.00	840.00	65.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,302.20	2,930.30	1,371.90	31.89
Approved Total (Overridden) (\$\$)		2,300.00		
(\$\$)	4,302.20	2,300.00	2,002.20	46.54
+ GST 7.00/7.00% (\$\$)	301.15	161.00	140.15	46.54
Nett Amount (\$\$)	4,603.35	2,461.00	2,142.35	46.54

INSPECTION

Date of Assignment:	10/08/2022	
Date Inspected:	08/08/2022 Inspected At:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2022)
Parts:	144	VOLKSWAGEN SCIROCCO 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV3983Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,045.00 FL	*1,045.00 FL
2	12		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
3	1		*REAR BUMPER BRACKET RH	Distorted	72.00 FL	*72.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	546.00 FL	*- FL
5	1		*REAR BUMPER CORNER RETAINER	Distorted	72.00 FL	*72.00 FL
6	1		*REAR BUMPER CORNER GARNISH	Deformed	165.00 FL	*165.00 FL
7	1		*REAR BUMPER REFLECTOR RH	Cut	72.00 FL	*72.00 FL
8	1		*REAR BUMPER CENTER DIFFUSER COVER	Mtg Cracked	450.00 FL	*450.00 FL
9	1		*REAR FENDER SPLASH SHIELD RH	Cracked	245.00 FL	*245.00 FL
10	8		*REAR FENDER SPLASH SHIELD CLIPS	Necessary	36.00 FL	*36.00 FL
11	1		*TAILLAMP	Cut	550.00 FL	*550.00 FL
12	1		*TAILLAMP GASKET RH	Serviceable	45.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,358.00	2,767.00
- List Item Discount on L Items 10.00/10.00% (S\$)	335.80	276.70
Total Parts (S\$)	3,022.20	2,490.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT REAR ELECTRICAL CHECK ,LOCKING SYSTEM ADJUST TAIL LAMP ETC	New	50.00	20.00
2	LABOUR CHARGE -PANEL BEATING ,REPAIRING OF TAILLAMP PANEL ,END PANEL AND PARTS REPLACEMENT	New	550.00	200.00
3	TO RESPRAY AFFECTED AREAS	New	680.00	220.00
Gross Labour Cost (\$\$)			1,280.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >