Adjuster Report 1/4/23, 1:57 PM

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way, #09-16

Our File No:

CC3/AIG22007490/EQCE2

Singapore 079120

Date:

OD

04/01/2023

**REFERENCE** 

Date of Loss:

Insured/Claimant:

PREMIUM LEASING PTE LTD

Policy No: Nature of Claim: 099993549

Claim No:

4546700501SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

01/08/2022

Reg No:

SMD8625U

Make & Model: (A)

AUDI A3, 999cc SEDAN TFSI S TRONIC (LED)

Engine No:

CHZ936774

51412 km

Reg. Date:

07/09/2018 (Man. Year: 2018)

Chassis No: Odometer:

WAUZZZ8VXJ1065657

Colour:

Black 999 cc

**Engine Capacity:** Market Value/New Car Price: S\$99,000.00

**Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Sum Insured (S\$):

Steering (Serviceable):

Footbrake (Serviceable): Yes

Yes

Handbrake (Serviceable):

**Engine Modification:** Yes

Pre-accident Condition: No

**CONDITION OF TYRES** 

Front Tyre Size: Front Left Side: Front Right Side: 205/55 R16 Continental 4 mm Continental 4 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 205/55 R16 Continental 4 mm

Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		20,255.00	11,671.68	8,583.32	42.38
Miscellaneous Items		0.00	0.00	0.00	
Labour		18,752.00	13,047.00	5,705.00	30.42
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	39,007.00	24,718.68	14,288.32	36.63
	- Excess (S\$)	1,200.00	1,200.00	0.00	0.00
	(S\$)	37,807.00	23,518.68	14,288.32	37.79
	+ GST 7.00/7.00% (S\$)	2,646.49	1,646.31	1,000.18	37.79
	Nett Amount (S\$)	40,453.49	25,164.99	15,288.50	37.79

INSPECTION

Date of Assignment: 11/08/2022

Date Inspected: 05/08/2022

24 Benoi Sector Singapore 629857 Inspected At: Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 14.0 days

Adjuster: **CHEN TSUE YEE** 

SHIAU CHAN Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,317.00 FS	*- FS
2	1		*REAR WHEEL HOUSING LINER ADAPTER - LH	Not Necessary	42.00 FS	*-FS
3	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	75.00 FS	*-FS
4	1		*REAR FENDER - LH	Dented	4,445.00 FS	*3,556.00 FS
5	1		*REAR WINDSCREEN	Necessary	905.00 FS	*724.00 FS
6	1		*REAR SIDE WINDOW - LH	Necessary	635.00 FS	*508.00 FS
7	2		*PRIMER	Necessary	44.00 FS	*34.72 FS
8	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	260.00 FS	*- FS
9	1		*FRONT DOOR - LH	Dented	3,265.00 FS	*2,612.00 FS
10	1		*FRONT DOOR OUTER SEAL - LH	Necessary	179.00 FS	*142.80 FS
11	1		*BONDING AGENT	Necessary	51.00 FS	*40.56 FS
12	1		*CLEANING SOLUTION	Necessary	74.00 FS	*58.96 FS
13	1		*APPLICATOR	Not Necessary	9.00 FS	*-FS
14	1		*FRONT DOOR ATTACHMENT PARTS - LH	Not Necessary	134.00 FS	*- FS
15	1		*FRONT DOOR CATCH - LH	Not Necessary	105.00 FS	*- FS
16	1		*FRONT DOOR MOUNTING BAR - LH	Not Necessary	182.00 FS	*- FS
17	1		*FRONT DOOR BOWDEN CABLE	Not Necessary	58.00 FS	*-FS
18	1		*FRONT WINDOW REGULATOR WITHOUT MOTOR - LH	Not Necessary	286.00 FS	*- FS
19	1		*FRONT DOOR HANDLE - LH	Not Necessary	398.00 FS	*- FS
20	1		*FRONT DOOR HANDLE HOUSING - LH	Repair	58.00 FS	*- FS
21	1		*REAR DOOR - LH	Dented	3,265.00 FS	*2,612.00 FS
22	1		*REAR DOOR OUTER SEAL - LH	Necessary	179.00 FS	*142.80 FS
23	1		*BONDING AGENT	Necessary	51.00 FS	*40.56 FS
24	1		*CLEANING SOLUTION	Necessary	74.00 FS	*58.96 FS
25	1		*APPLICATOR	Not Necessary	9.00 FS	*-FS
26	1		*REAR DOOR ATTACHMENT PARTS - LH	Not Necessary	252.00 FS	*-FS
27	1		*REAR DOOR CATCH - LH	Not Necessary	116.00 FS	*- FS
28	1		*REAR ALUMINIUM RIM - LH	Not Necessary	1,303.00 FS	*-FS
29	1		*RUBBER VALVE	Not Necessary	4.00 FS	*-FS
30	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
31	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
32	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
33	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
34	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
35	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
36	1		*SUNDRIES	Necessary	400.00 FS	*60.32 FS
	•	part. S=Spcl			100.0010	
				Total Darta (CC)		44 674 60

Total Parts (S\$) 20,255.00 11,671.68

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REINSTALL REAR PARKING AID	New	280.00	280.00
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER	New	600.00	600.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS	New	400.00	0.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	150.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	1,400.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	) New	1,400.00	1,400.00
7	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	S New	700.00	700.00
8	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,300.00	4,000.00
9	TO RESPRAY REAR BUMPER, LHS REAR DOOR, DOOR HANDLE, LHS FRONT DOOR, LHS REAR FENDER, ROOF CHANNEL, LHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES AND REAR END PANELLING	New	7,000.00	4,325.00
10	TO RENEW LHS REAR RIM. TO CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labou	ır Cost (S\$)	18,752.00	13,047.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >