

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAI	NCE BHD	Ref:	CS3/LPC22007491/Kvy3e2	
	300 BEACH ROAD #17-04/07 THE CC) NCOURSESINGAPORE 19955	Date:	15/08/2022	
			Code	: LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XB 9997U	Veh. Inspected	YP 2170Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	22/22/22/VC05/026113	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	05/08/2022	
2.	Vehicle Particulars & Condition				
	Make & Model	ISUZU FVR34SUQDC (A)	c.c	7790	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JALFVR347G7000299	Colour	WHITE	
	Odometer	166588 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	275/70 R22.5	FIRENZA	7 mm	
	L/H Front Tyre	275/70 R22.5	FIRENZA	7 mm	
	R/H Rear Tyre	275/70 R22.5 (D)	GOODYEAR	8/8 mm	
	L/H Rear Tyre	275/70 R22.5 (D)	GOODYEAR	8/8 mm	
4. Description of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE R			
5.	General Information				
	Accident Date	02/08/2022	Inspect Date / Time	08/08/2022 (01:43 PM)	
	Survey held at	EXCEL MOTOR	•		
		BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-297 SINGAPORE 569535			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22007491/Kvy3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$