

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CC3/AIS22007494/EQY3Q2**Date:** 15/09/2022**REFERENCE**

Insured/Claimant:	NG SOO YEE	Policy No:	SP2001026621	
Date of Loss:	16/07/2022	Nature of Claim:	OD	Claim No: 202222005682

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA1515P		
Make & Model:	VOLKSWAGEN BEETLE CABRIOLET, 1.2 TSI DSG (A)	Engine No:	CYV643083
Reg. Date:	28/02/2020 (Man. Year: 2019)	Chassis No:	WVWZZZ16ZKM505720
Colour:	Black	Odometer:	29997 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	S\$116,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,600.32	1,457.91	1,142.41	43.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	1,750.00	2,180.00	55.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,530.32	3,207.91	3,322.41	50.88
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	5,930.32	2,607.91	3,322.41	56.02
+ GST 7.00/7.00% (\$\$)	415.12	182.55	232.57	56.02
Nett Amount (\$\$)	6,345.44	2,790.46	3,554.98	56.02

INSPECTION

Date of Assignment:	05/08/2022	
Date Inspected:	05/08/2022	Inspected At: Volkswagen Centre Singapore (Tuas) 17 TUAS AVENUE Singapore 639176
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Sep 2022)	
Parts:	N/A	VOLKSWAGEN BEETLE CABRIOLET 1.2 TSI DSG (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA1515P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Broken	1,096.62 FS	*1,096.62 FS
2	1		*BUMPER BRACKET REINFORCEMENT	Not Necessary	554.41 FS	*- FS
3	1		*CROSS MEMBER	Not Necessary	147.51 FS	*- FS
4	1		*FOAM INSERT REINFORCEMENT FOAM (SIDE)	Not Necessary	115.21 FS	*- FS
5	1		*FOAM INSERT REINFORCEMENT FOAM (UPPER)	Not Necessary	24.88 FS	*- FS
6	1		*HOLDER FOR COVER BUMPER BUMPER UPPER HOLDER LH	Broken	38.87 FS	*38.87 FS
7	1		*HOLDER FOR COVER BUMPER BUMPER UPPER HOLDER RH	Broken	38.87 FS	*38.87 FS
8	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Not Necessary	31.17 FS	*- FS
9	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Not Necessary	31.17 FS	*- FS
10	4		*RIVET	Not Necessary	2.45 FS	*- FS
11	1		*GRILLE SATIN BLACK/BRIGHT BUMPER CTR LOWER GRILLE	Cut	257.83 FS	*257.83 FS
12	1		*GRILLE BLACK /SATIN BLACK/LHS FOG LAMP GRILLE	Not Necessary	150.31 FS	*- FS
13	2		*FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING	Not Necessary	31.02 FS	*- FS
14	1		*FRT NUMBER PLATE	Broken	80.00 FS	*25.72 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 2,600.32 1,457.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	200.00	200.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	360.00	360.00
3	TO ALIGN LED HEADLIGHT	New	100.00	100.00
4	LABOUR	New	1,680.00	560.00
5	SPRAY PAINT	New	1,590.00	530.00
Gross Labour Cost (\$)			3,930.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >