



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 5879K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
2	FORK INNER TUBES	NOT NECESSARY	480.00	-
2	FORK OUTER TUBER	NOT NECESSARY	520.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	265.00	-
1	FRONT SPORT RIM	NOT NECESSARY	520.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	420.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	108.00	-
1	FRONT RIM BEARING	NOT NECESSARY	88.00	-
1	FRONT SIDE COVER (MATT) - R/H	CUT	220.00	220.00
1	SET SIDE MIRRORS	CUT	180.00	180.00
1	SET HANDLE-BAR	BENT	350.00	280.00
1	HANDLE-BAR END O/S	CUT	105.00	40.00
1	SET HANDLE GRIP	NOT NECESSARY	80.00	-
1	SET BRAKE LEVER	CUT	185.00	185.00
1	FRONT FOOTREST - R/H	NOT NECESSARY	105.00	-
1	FRONT FOOTREST BRACKET - R/H	NOT NECESSARY	195.00	-
1	BRAKE PEDAL	CUT	148.00	148.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	1,580.00	-
1	EXHAUST PROTECTOR	CUT	180.00	180.00
1	EXHAUST END COVER	CUT	78.00	78.00
1	SET FAIRING ASSY	TO REPAIR SEE LABOUR	1,200.00	-
	LESS 10% DISCOUNT		-700.70	-131.10
			6,306.30	1,179.90
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET NUMBER PLATE (SN)	NOT NECESSARY	38.00	-
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	95.00	-
1	REAR BOX (SN)	CUT	580.00	450.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-

Report Ref No. CS/AGI22007499/Uvy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ENGINE SLIDER (SN)	CUT	380.00	200.00
1	SET FAIRING COVER STICKER (SN)	SCRATCHED	800.00	500.00
			2,159.00	1,150.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE BODY FRAME REPAIR.	NOT NECESSARY	480.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF EXHAUST ASSY AND 1 SET FAIRING ASSY.		520.00	380.00
			1,080.00	380.00
<b>GRAND TOTAL</b>			<b>9,545.30</b>	<b>2,709.90</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,150.00</b>

Report Ref No. CS/AGI22007499/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.