



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2206986
3 ANSON ROAD #16-00	INV Date	10/11/2022
SPRINGLEAF TOWER	Reference	CC6/CTI22007506/Upa3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	YQ 1799L
Insured Veh.	GZ 5360H
Claim No.	SNM22D205494/C02
Policy No.	DMCVSNW00053662200
Accident Date	04/08/2022
Inspection Date	05/08/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI22007506/Upa3q2 Date: 10/11/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GZ 5360H	Veh. Inspected	YQ 1799L
Policy No.	DMCVSNW00053662200	Coverage (\$)	0.00
Claim No.	SNM22D205494/C02	Excess (\$)	0.00
Assign From		Assign Date	05/08/2022
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI CANTER FEB71	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	FEB71EA30066	Colour	RED
Odometer	132177 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/75 R17.50	AUSTONE	6 mm
L/H Front Tyre	215/75 R17.50	AUSTONE	6 mm
R/H Rear Tyre	215/75 R17.50 (D)	AUSTONE	6/6 mm
L/H Rear Tyre	215/75 R17.50 (D)	AUSTONE	6/6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/08/2022	Inspection Date	05/08/2022
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 1799L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT RH DOOR	DENTED /BENT	1,995.00	1,995.00
2	FRONT RH DOOR HINGE @\$144.50	LOWER BENT	289.00	144.50
1	FRONT RH DOOR 'BLUETEC' STICKER	NOT NECESSARY	86.50	-
1	FRONT RH DOOR MIRROR	BROKEN	217.80	217.80
1	FRONT RH DOOR MIRROR BRACKET	TO REPAIR SEE LABOUR	545.20	-
1	FRONT RH DOOR OUTER PILLAR	TO REPAIR SEE LABOUR	1,482.40	-
1	FRONT RH SIGNAL LAMP	BROKEN	324.30	324.30
1	FRONT RH HEAD LAMP	CRACKED	856.40	856.40
1	FRONT RH HEAD LAMP SIDE COVER FRONT RH	NOT NECESSARY	187.50	-
1	FRONT RH SIDE LAMP	BROKEN	325.20	325.20
1	FRONT RH BUMPER PROTECTOR	GRAZED	375.00	375.00
1	FRONT RH CORNER PANEL GARNISH	CUT	592.10	592.10
1	FRONT RH GRILLE	TO REPAIR SEE LABOUR	1,105.70	-
	LESS 25% DISCOUNT		-	-1,207.58
			8,382.10	3,622.72
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT RH SIGNAL LAMP CLIPS (SN)	NOT NECESSARY	20.00	-
1	SET FRONT RH HEAD LAMP CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET FRONT RH BUMPER PROTECTOR CLIP (SN)	NECESSARY	40.00	40.00
1	SET FRONT RH GRILLE CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT RH 'CORPORATE' ADVERTIEMENT & ARTWORK (SN)	NECESSARY	200.00	100.00
			340.00	140.00
<u>LABOUR</u>				
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION .		50.00	20.00
	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF FRONT RH DOOR MIRROR BRACKET ,FRONT RH DOOR OUTER PILLAR AND FRONT RH GRILLE .		800.00	550.00

Report Ref No. CC6/CTI22007506/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS .		700.00	600.00
	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		50.00	30.00
	TO REMOVE ,REPLACE AND TRANSFER DOOR PANEL ,FITTING AND MECHANISMS.		80.00	60.00
			1,680.00	1,260.00
	GRAND TOTAL		10,402.10	5,022.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00

Report Ref No. CC6/CTI22007506/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YQ 1799L

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YQ 1799L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

