

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007507/AVCE2**Date:** 16/11/2022REFERENCE

Insured/Claimant:	ROBIN PAITIMUSA	Policy No:	2100403389	
Date of Loss:	06/07/2022	Nature of Claim:	OD	Claim No: 7393503457SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR4899Y		
Make & Model:	AUDI A3, 1.4 TFSI AMBIENTE (NAV) MY 15 (A)	Engine No:	CZC217924
Reg. Date:	11/02/2015 (Man. Year: 2014)	Chassis No:	WAUZZZ8V1F1054960
Colour:	Bronze	Odometer:	198334 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$46,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,455.00	2,203.20	2,251.80	50.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,872.00	1,522.00	2,350.00	60.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,327.00	3,725.20	4,601.80	55.26
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	7,727.00	3,125.20	4,601.80	59.55
+ GST 7.00/7.00% (S\$)	540.89	218.76	322.13	59.56
Nett Amount (S\$)	8,267.89	3,343.96	4,923.93	59.55

INSPECTION

Date of Assignment:	08/08/2022		
Date Inspected:	05/08/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,201.00 FS	*1,760.80 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	201.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	36.00 FS	*- FS
4	2		*REAR BUMPER LOCKING MECHANISM	Not Necessary	67.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Cut	264.00 FS	*210.80 FS
6	1		*REAR BUMPER SIDE REINFORCEMENT	Not Necessary	642.00 FS	*- FS
7	2		*REAR BUMPER BRACKET - LH / RH	Not Necessary	30.00 FS	*- FS
8	2		*REAR PARKING AID SENSOR	Necessary	530.00 FS	*195.12 FS
9	4		*REAR SEAL RING	Not Necessary	10.00 FS	*- FS
10	1		*REAR LIGHT REFLECTOR - LH	Cut	46.00 FS	*36.48 FS
11	1		*EXHAUST TAIL PIPE CHROME TRIM - LH	Not Necessary	128.00 FS	*- FS
12	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	4,455.00 2,203.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,872.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >