

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22007508/AVCM4**Date:** 16/12/2022**REFERENCE**

Insured/Claimant: VOESTALPINE HIGH PERFORMANCE METALS  
Date of Loss: 31/07/2022

Policy No: 2070164200  
Nature of Claim: OD Claim No: 2493793820SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMW4249Z**  
Make & Model: AUDI A5, 2.0 SPORTBACK (A)  
Reg. Date: 20/11/2020 (Man. Year: 2020)  
Colour: Grey  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$180,000.00  
Sum Insured (\$\$): **Market Value/New Car Price**

Engine No: DEM026164  
Chassis No: WAUZZZF52MA007422  
Odometer: 10275 km

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18  
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                | 8,133.00          | 4,057.92          | 4,075.08          | 50.11         |
| Miscellaneous Items                  | 0.00              | 0.00              | 0.00              |               |
| Labour                               | 5,952.00          | 2,402.00          | 3,550.00          | 59.64         |
| Paintwork Labour                     | 0.00              | 0.00              | 0.00              |               |
| Towing                               | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b> | <b>14,085.00</b>  | <b>6,459.92</b>   | <b>7,625.08</b>   | <b>54.14</b>  |
| <b>- Excess (\$\$)</b>               | 1,600.00          | 1,600.00          | 0.00              | 0.00          |
| <b>(\$\$)</b>                        | 12,485.00         | 4,859.92          | 7,625.08          | 61.07         |
| <b>+ GST 7.00/7.00% (\$\$)</b>       | 873.95            | 340.19            | 533.76            | 61.07         |
| <b>Nett Amount (\$\$)</b>            | <b>13,358.95</b>  | <b>5,200.11</b>   | <b>8,158.84</b>   | <b>61.07</b>  |

**INSPECTION**

Date of Assignment: 08/08/2022

Date Inspected: 05/08/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                                 | Distorted     | 2,609.00 FS | *2,087.20 FS |
| 2   | 1   |          | *REAR BUMPER SECURING STRIP - UPPER          | Necessary     | 125.00 FS   | *100.00 FS   |
| 3   | 1   |          | *REAR BUMPER SECURING STRIP - LOWER          | Necessary     | 249.00 FS   | *198.80 FS   |
| 4   | 1   |          | *REAR BUMPER SPOILER                         | Cut           | 276.00 FS   | *220.80 FS   |
| 5   | 1   |          | *REAR BUMPER BRACKET - LH                    | Not Necessary | 228.00 FS   | *- FS        |
| 6   | 2   |          | *REAR BUMPER REFLECTOR - LH /RH              | Not Necessary | 96.00 FS    | *- FS        |
| 7   | 1   |          | *REAR BUMPER OUTER TAIL LIGHT - LH           | Cracked       | 1,269.00 FS | *1,015.20 FS |
| 8   | 1   |          | *REAR BUMPER OUTER TAIL LIGHT TRIM - LH      | Not Necessary | 34.00 FS    | *- FS        |
| 9   | 1   |          | *REAR BUMPER GUIDE SECTION - LH / RH - UPPER | N/S cracked   | 52.00 FS    | *20.16 FS    |
| 10  | 1   |          | *REAR BUMPER GUIDE SECTION - LH - LOWER      | Cracked       | 49.00 FS    | *39.04 FS    |
| 11  | 1   |          | *REAR BUMPER HOLDING STRAP - LH              | Not Necessary | 94.00 FS    | *- FS        |
| 12  | 1   |          | *GUIDE SECTION PIN                           | Not Necessary | 3.00 FS     | *- FS        |
| 13  | 1   |          | *REAR BUMPER REINFORCEMENT BEAM              | Not Necessary | 1,131.00 FS | *- FS        |
| 14  | 2   |          | *REAL BUMPER SEAL                            | Not Necessary | 32.00 FS    | *- FS        |
| 15  | 2   |          | *REAR PARKING AID SENSOR - INNER /OUTER      | Not Necessary | 531.00 FS   | *- FS        |
| 16  | 1   |          | *REAR PARKING AID SENSOR - SIDE              | Not Necessary | 266.00 FS   | *- FS        |
| 17  | 4   |          | *REAR PARKING AID SEAL RING                  | Not Necessary | 10.00 FS    | *- FS        |
| 18  | 1   |          | *REAR FENDER TRIM                            | Cracked       | 75.00 FS    | *59.52 FS    |
| 19  | 1   |          | *REAR EXHAUST TAIL PIPE CHROME TRIM - LH     | Cut           | 383.00 FS   | *306.00 FS   |
| 20  | 1   |          | *AERIAL RETAINER - LH                        | Not Necessary | 29.00 FS    | *- FS        |
| 21  | 1   |          | *TELEPHONE AERIAL                            | Not Necessary | 192.00 FS   | *- FS        |
| 22  | 1   |          | *SUNDRIES                                    | Necessary     | 400.00 FS   | *11.20 FS    |

F=Franchise part. S=SpcNett.

|                         |                 |                 |
|-------------------------|-----------------|-----------------|
| <b>Total Parts (\$)</b> | <b>8,133.00</b> | <b>4,057.92</b> |
|-------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars  | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>             |  |          |                 |                 |
| 1                               | TO REMOVE AND TRANSFER REAR PARKING AID AND READ LID KICK SENSOR   | New      | 360.00          | 360.00          |
| 2                               | TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR LHS REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New      | 2,400.00        | 750.00          |
| 3                               | TO RESPRAY REAR BUMPER, LHS REAR FENDER, REAR END PANELLING  | New      | 3,000.00        | 1,100.00        |
| 4                               | TO CARRY OUT DIAGNOSTIC CHECK  | New      | 192.00          | 192.00          |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>5,952.00</b> | <b>2,402.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >