

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007509/ACE2**Date:** 01/02/2023**REFERENCE**

Insured/Claimant:	CHAN YU HUI	Policy No:	207015336		
Date of Loss:	30/07/2022	Nature of Claim:	OD	Claim No:	8562360815SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS3121Y				
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC04268		
Reg. Date:	05/11/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF38M1018780		
Colour:	White	Odometer:	18809 km		
Engine Capacity:	1395 cc				
Market Value/New Car Price:	S\$165,000.00				
Sum Insured (S\$):	Market Value/New Car Price				

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,848.00	10,074.48	19,773.52	66.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,632.00	6,082.00	8,550.00	58.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,480.00	16,156.48	28,323.52	63.68
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	44,080.00	15,756.48	28,323.52	64.25
+ GST 8.00/8.00% (S\$)	3,526.40	1,260.52	2,265.88	64.25
Nett Amount (S\$)	47,606.40	17,017.00	30,589.40	64.25

INSPECTION

Date of Assignment:	08/08/2022		
Date Inspected:	05/08/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BUMPER	Deformed	1,585.00 FS	*1,267.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	433.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	66.00 FS	*- FS
4	1		*FRONT BUMPER CENTER TRIM	Not Necessary	396.00 FS	*- FS
5	1		*FRONT BUMPER LOWER GRILLE - CENTER	Not Necessary	242.00 FS	*- FS
6	2		*FRONT BUMPER PARKING AID SENSOR SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
7	1		*FRONT BUMPER LOWER GRILLE COVER - CENTER	Not Necessary	58.00 FS	*- FS
8	1		*FRONT BUMPER LOWER CLOSING ELEMENT	Not Necessary	212.00 FS	*- FS
9	1		*FRONT BUMPER SPOILER	Repair	850.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	171.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE TRIM - RH	Not Necessary	182.00 FS	*- FS
12	1		*FRONT PARKING AID SENSOR SUPPORT - RH	Not Necessary	29.00 FS	*- FS
13	1		*RADIATOR GRILLE	Cracked	2,135.00 FS	*1,708.00 FS
14	1		*REAR STRIKER PLATE	Not Necessary	271.00 FS	*- FS
15	1		*COVER CAP	Not Necessary	256.00 FS	*- FS
16	1		*BRACKET	Not Necessary	46.00 FS	*- FS
17	1		*SECURING PLATE	Not Necessary	37.00 FS	*- FS
18	1		*FRONT COVER	Cracked	271.00 FS	*216.80 FS
19	1		*FRONT CAMERA	Not Necessary	1,264.00 FS	*- FS
20	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	114.00 FS	*- FS
21	1		*FRONT BUMPER CARRIER	Not Necessary	974.00 FS	*- FS
22	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	43.00 FS	*- FS
23	1		*FRONT BUMPER TOP COVER	Cracked	137.00 FS	*109.60 FS
24	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
25	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
26	1		*HORN SIGNAL LOW TONE - RH	Not Necessary	146.00 FS	*- FS
27	1		*HORN BRACKET - RH	Not Necessary	25.00 FS	*- FS
28	1		*BONNET	Dented	3,695.00 FS	*2,956.00 FS
29	2		*BONNET HINGE - LH / RH	Not Necessary	162.00 FS	*- FS
30	1		*BONNET ATTACHMENT PARTS	Not Necessary	309.00 FS	*- FS
31	1		*BONNET STRIKER - RH	Not Necessary	123.00 FS	*- FS
32	1		*BONNET SOUND ABSORBER	Not Necessary	244.00 FS	*- FS
33	1		*EXHAUST IMPACT PROTECTION - CENTER	Necessary	31.00 FS	*24.24 FS
34	1		*BONNET LID LOCK MICRO - SWITCH - RH	Not Necessary	228.00 FS	*- FS
35	1		*BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
36	1		*BONNET RELEASE ELEMENT	Not Necessary	65.00 FS	*- FS
37	1		*BONNET RELEASE LEVER	Not Necessary	16.00 FS	*- FS
38	1		*BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
39	2		*FRONT PARKING AID SENSOR - LH / RH	Not Necessary	531.00 FS	*- FS
40	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
41	1		*HEADLIGHT MAIN BEAM MOUNTING - RH	Cracked	132.00 FS	*105.20 FS
42	1		*HEADLIGHT - RH	Not Necessary	5,952.00 FS	*- FS
43	1		*LIFT CYLINDER - RH	Not Necessary	231.00 FS	*- FS
44	1		*LIFT CYLINDER HOSE	Not Necessary	92.00 FS	*- FS
45	1		*FRONT RADIATOR AIR GUIDE - RH	Not Necessary	43.00 FS	*- FS
46	1		*FRONT RADIATOR AIR GUIDE - UPPER	Not Necessary	48.00 FS	*- FS
47	1		*FRONT TEMPERATURE SENSOR HOLDER	Not Necessary	9.00 FS	*- FS
48	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,132.00 FS	*904.80 FS
49	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
50	1		*REAR BUMPER	Deformed	1,738.00 FS	*1,390.40 FS
51	1		*REAR BUMPER SPOILER	Deformed	510.00 FS	*408.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*REAR BUMPER SUPPORT - CENTER	Not Necessary	108.00 FS	*- FS
53	1		*REAR BUMPER GRILLE - RH	Not Necessary	170.00 FS	*- FS
54	1		*REAR PARKING AID SENSOR SUPPORT - RH	Not Necessary	28.00 FS	*- FS
55	1		*REAR BUMPER ADAPTER - RH	Not Necessary	95.00 FS	*- FS
56	1		*REAR BUMPER BRACKET	Not Necessary	53.00 FS	*- FS
57	1		*REAR BUMPER REFLECTOR - RH	Not Necessary	46.00 FS	*- FS
58	1		*REAR OPENING BOOT LID CONTROL UNIT	Not Necessary	484.00 FS	*- FS
59	1		*AERIAL ACCESS KEY	Not Necessary	79.00 FS	*- FS
60	1		*REAR BUMPER SHOCK ABSORBER	Not Necessary	95.00 FS	*- FS
61	1		*REAR BUMPER CARRIER	Not Necessary	693.00 FS	*- FS
62	2		*REAR BUMPER HOLDING STRAP - LH / RH	Not Necessary	64.00 FS	*- FS
63	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	71.00 FS	*- FS
64	2		*REAR PARKING AID SENSOR - LH / RH	Not Necessary	531.00 FS	*- FS
65	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
66	1		*ADHESIVE TAPE	Not Necessary	21.00 FS	*- FS
67	1		*REAR AUDI EMBLEM	Not Necessary	144.00 FS	*- FS
68	1		*Q3 INSCRIPTION CHROME	Not Necessary	104.00 FS	*- FS
69	2		*REAR WHEEL COVER - LH / RH	Necessary	1,132.00 FS	*904.80 FS
70	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
71	1		*UNDERBODY TRIM - RH	Not Necessary	58.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	29,848.00	10,074.48
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENT. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES AND BOTH FRONT WHEEL ARCH TRIMS	New	4,000.00	2,050.00
5	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
6	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	500.00
7	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS	New	4,000.00	1,500.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			14,632.00	6,082.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >