

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22007514/RVCQ2**Date:** 14/09/2022**REFERENCE**

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SLW9039S **Insured Vehicle No :** SMR3828K
 Date of Loss: 30/07/2022 Nature of Claim: TP Claim No: DMCF2200163H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW9039S**
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 2ZR0A56927
 Reg. Date: 08/03/2018 (Man. Year: 2017) Chassis No: JTDGG20WX0J008904
 Colour: Maroon Odometer: 50257 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,167.67	602.25	565.42	48.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	900.00	800.00	47.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,867.67	1,502.25	1,365.42	47.61
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	2,867.67	1,200.00	1,667.67	58.15

INSPECTION

Date of Assignment: 08/08/2022
 Date Inspected: 10/08/2022 Inspected At: 28 SURREY ROAD SINGAPORE 307762
 Estimated Period of Repair: 3.0 days Repairer: Choon Hock Motor Trading Co (HQ)

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Sep 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW9039S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	570.00 FL	*570.00 FL
2	1		*REAR BUMPER REFLECTOR LH	Cracked	56.00 FL	*56.00 FL
3	1		*REAR BUMPER SIDE RETAINER LH	Cracked	44.00 FL	*44.00 FL
4	1		*REAR BUMPER BRACKET LH	Bent	93.00 FL	*93.00 FL
5	1		*REAR PANEL ASSY	Repair	453.90 FL	*- FL
6	1		*SET REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
7	1		*SET BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					1,471.90	793.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					304.23	190.75
Total Parts (\$\$)					1,167.67	602.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	300.00
2	SPRAY PAINTING	New	800.00	600.00
3	RUSTPROOFING	New	100.00	0.00
Gross Labour Cost (\$)			1,700.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >