

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22007516/AVY3Q2**Date:** 01/11/2022**REFERENCE**

Insured/Claimant:	Law Johnny	Policy No:	SP2000683520-01	
Date of Loss:	03/08/2022	Nature of Claim:	OD	Claim No: 202222005977SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT7798M		
Make & Model:	MERCEDES-BENZ GLC250D, 2.1 4MATIC (A)	Engine No:	65192134164018
Reg. Date:	05/12/2017 (Man. Year: 2017)	Chassis No:	WDC2539092F285839
Colour:	Blue	Odometer:	84173 km
Engine Capacity:	2143 cc		
Market Value/New Car Price:	S\$152,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R20	Rear Tyre Size:	255/45 R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,757.30	13,287.00	5,470.30	29.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,180.00	700.00	37.23
Paintwork Labour	1,000.00	800.00	200.00	20.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,637.30	15,267.00	6,370.30	29.44
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	21,337.30	14,967.00	6,370.30	29.86
+ GST 7.00/7.00% (S\$)	1,493.61	1,047.69	445.92	29.86
Nett Amount (S\$)	22,830.91	16,014.69	6,816.22	29.86

INSPECTION

Date of Assignment:	06/08/2022	Present Location:	Success United Pte Ltd (HQ)
Date Inspected:	08/08/2022	Inspected At:	Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Nov 2022)

Parts: 143 MERCEDES-BENZ GLC250D 2.1 4MATIC (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT7798M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRT BONNET (WCP)	Dented	1,200.00 F	*1,200.00 F
2	2	*FRT BONNET HINGE L/R (WCP)	Bent	300.00 F	*300.00 F
3	2	*FRT BONNET DAMPER ABSORBER L/R (WCP)	Not Necessary	160.00 F	*- F
4	1	*FRT BONNET WEATHERSTRIP (WCP)	Not Necessary	50.00 F	*- F
5	1	*FRT BONNET MERCEDES LOGO (WCP)	Necessary	35.00 F	*35.00 F
6	2	*FRT BONNET TOP HOOK LOCK L/R (WCP)	Damaged	64.00 F	*64.00 F
7	1	*FRT BONNET CENTRE TOP LOCK LEVER	Bent	45.00 F	*45.00 F
8	1	*FRT BONNET LOCK SPRING L/R (WCP)	O/S Damaged	50.00 F	*25.00 F
9	1	*FRT BONNET LOCK PANEL (WCP)	Not Necessary	28.00 F	*- F
10	1	*FRT BONNET LOCK CABLE (WCP)	Damaged	68.00 F	*68.00 F
11	2	*FRT FENDER L/R (WCP)	Distorted	900.00 F	*900.00 F
12	1	*FRT FENDER GUARD RH (WCP)	Cut	155.00 F	*165.00 F
13	2	*HEADLAMP ASSY L/R (WCP)	O/S Smashed / N/S Cracked	3,300.00 F	*3,300.00 F
14	2	*HEADLAMP BRACKET L/R (WCP)	Damaged	76.00 F	*76.00 F
15	1	*FRT GRILLE BRACKET (WCP) }	Smashed	42.00 F	*- F
16	1	*FRT GRILLE ASSY (WCP) }	Smashed	600.00 F	*280.00 F
17	1	*FRT GRILLE MERCEDES LOGO (WCP)	Smashed	120.00 F	*90.00 F
18	1	*FRT CAMERA UNIT (WCP)	Not Necessary	1,050.00 F	*- F
19	1	*FRT BUMPER UNDER SHIELD COVER (WCP)	Cracked	195.00 F	*195.00 F
20	1	*FRT BUMPER ASSY (WCP)	Distorted	850.00 F	*850.00 F
21	1	*FRT BUMPER SIDE HOLDER L/R (WCP)	O/S Damaged	50.00 F	*25.00 F
22	2	*FRT BUMPER BRACKET L/R (WCP)	Damaged	90.00 F	*90.00 F
23	1	*FRT BUMPER INNER BASE FRAME SUPPORT (WCP)	Cracked	150.00 F	*150.00 F
24	1	*FRT BUMPER INNER SPONGE (WCP)	Cracked	110.00 F	*110.00 F
25	1	*FRT BUMPER REINFORCEMENT (WCP)	Bent	300.00 F	*300.00 F
26	2	*FRT BUMPER REINFORCEMENT BRACKET L/R (WCP)	Not Necessary	290.00 F	*- F
27	1	*FRT BUMPER TOW HOOK COVER (WCP)	Missing	38.00 F	*38.00 F
28	1	*FRT BUMPER LOWER AIR GRILLE (WCP)	Cracked	195.00 F	*195.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
29	1	*FRT BUMPER LOWER EXTENSION (WCP)	Deformed	220.00 F	*106.00 F
30	1	*FRT BUMPER LOWER CENTRE CHROME TRIM (WCP)	Cracked	385.00 F	*385.00 F
31	6	*FRT BUMPER PARKING SENSO PDC (WCP)	Not Necessary	750.00 F	*- F
32	1	*FRT NO. PLATE GARNISH (WCP)	Deformed	83.00 F	*83.00 F
33	1	*FRT PARKING SENSOR WIRE HARNESS (WCP)	Not Necessary	135.00 F	*- F
34	1	*RADIATOR SUPPORT PANEL ASSY (WCP)	Buckled	320.00 F	*320.00 F
35	2	*RADIATOR SUPPORT BRACE PANEL L/R (WCP)	Bent	136.00 F	*68.00 F
36	1	*HORN (WCP)	Not Necessary	135.00 F	*- F
37	1	*RADIATOR ASSY (WCP)	Cracked	700.00 F	*700.00 F
38	2	*RADIATOR SIDE AIR GUIDE DUCT L/R (WCP)	Deformed	134.00 F	*134.00 F
39	1	*AIRCON CONDENSER (WCP)	Dented	825.00 F	*825.00 F
40	1	*AIRCON LIQUID PIPE (WCP)	Not Necessary	195.00 F	*- F
41	1	*RADIATOR LOWER SUPPORT (WCP)	Not Necessary	135.00 F	*- F
42	1	*FRT BUMPER SIDE FOGLAMP COVER L/R (WCP)	O/S Deformed	106.00 F	*53.00 F
43	1	*AIR INTAKE DUCT (WCP)	Cracked	175.00 F	*175.00 F
44	1	*OUTSIDE TEMPERATURE SENSOR (WCP)	Not Necessary	58.00 F	*- F
45	1	*FRT WINDSCREEN SIDE TRIM MOULDING LH (WCP)	Not Necessary	135.00 F	*- F
46	1	*RADIATOR AUXILIARY FAN ASSY (WCP)	Not Necessary	980.00 F	*- F
47	1	*BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
48	1	*FENDER INNER LINER CLIPS	Necessary	40.00 FS	*40.00 FS
49	1	*FRT NO. PLATE W/FRAME	Missing	40.00 FS	*40.00 FS
50	1	*FRT FENDER INNER LINER RH (FRT) (WCP)	Not Necessary	130.00 F	*- F
51	1	*FRT FENDER INNER LINER RH (REAR) (WCP)	Not Necessary	85.00 F	*- F
Supplementary #1					
52	1	*FRT BONNET INSULATOR (WCP)	Crumpled	190.00 F	*190.00 F
53	1	*FRT FENDER GUARD LH (WCP)	Damaged	155.00 F	*155.00 F
54	1	*BONNET LINE FASTENER (WCP)	Damaged	15.00 F	*25.00 F
Supplementary #2					
55	2	*BONNET MECHANISM LOCK L/R (WCP)	Damaged	150.00 F	*150.00 F
56	2	*BONNET LOCK SWITCH L/R (WCP)	Damaged	100.00 F	*100.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	17,063.00	12,090.00
+ Margin on L,N Items 10.00/10.00% (S\$)	1,694.30	1,197.00
Total Parts (S\$)	18,757.30	13,287.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA.	New	1,000.00	800.00
Labour Items				
2	TO REMOVE, REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTING.	New	80.00	30.00
3	TO REMOVE, REINSTAL AIRCON PARTS, VACUM, REFILL GAS.	New	300.00	150.00
4	TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT.	New	1,500.00	1,000.00
Gross Labour Cost (\$)			2,880.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >