

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 1120H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID (CONSISTENT)	BENT / BUCKLED	3,380.70	3,108.00
1	BOOTLID REAR LOGO (CONSISTENT)	NECESSARY	158.00	125.00
1	BOOTLID 'TFSI' EMBLEM (CONSISTENT)	NECESSARY	142.00	90.00
1	BOOTLID 'A6' EMBLEM (CONSISTENT)	NECESSARY	98.00	85.00
2	BOOTLID REFLECTORS @\$990.00(CONSISTENT)	CUT / CRACKED	1,980.00	1,640.00
1	BOOTLID INNER TRIM (CONSISTENT)	NOT NECESSARY	331.00	-
1	BOOTLID INNER LOCK (CONSISTENT)	TWISTED	566.80	550.00
1	BOOTLID WEATHERSTRIP (CONSISTENT)	TWISTED	385.50	282.00
1	BOOTLID OUTER CHROME MOULDING (CONSISTENT)	SCRATCHED / NECESSARY	650.00	495.00
1	REAR BUMPER (CONSISTENT)	DISTORTED	2,245.20	2,018.00
1	SET REAR BUMPER BEAM (CONSISTENT)	DISTORTED	844.50	815.00
2	REAR BUMPER SIDE RETAINERS @\$95.00(CONSISTENT)	BENT	190.00	190.00
1	REAR BUMPER LOWER SKIRTING (CONSISTENT)	DISTORTED	850.00	320.00
4	REAR BUMPER PDC SENSORS @\$225.00(CONSISTENT)	SHORTED (3 PCS ONLY)	900.00	675.00
1	REAR ANTENNA SENSOR (CONSISTENT)	CRACKED	350.00	205.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	80.00	60.00
1	REAR BUMPER TOW COVER (CONSISTENT)	DEFORMED	60.00	35.00
1	REAR BUMPER INNER TOP RETAINER (CONSISTENT)	CRACKED	310.00	188.00
2	REAR BUMPER EXHAUST CHROMES @\$280.00 (CONSISTENT)	BENT	560.00	560.00
	REAR EXHAUST ASSY(CONSISTENT)	TO REPAIR SEE LABOUR	2,245.00	-
2	REAR EXHAUST MOUNTINGS @\$60.00(CONSISTENT)	NOT NECESSARY	120.00	-
1	REAR EXHAUST HEAT SHIELD (CONSISTENT)	BENT	366.00	302.00
1	REAR END PANEL (CONSISTENT)	BADLY DENTED	815.00	610.00
1	REAR END PANEL INNER (CONSISTENT)	BADLY DENTED	655.00	545.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	TWISTED	486.90	182.00
1	REAR FENDER FLOOR PANEL (CONSISTENT)	CRUMPLED / BUCKLED	2,555.10	2,210.00
1	REAR FLOOR PANEL TOP BOARD (CONSISTENT)	NOT NECESSARY	627.20	-
1	REAR FLOOR PANEL TOOLS SPONGE (CONSISTENT)	NOT NECESSARY	568.00	-

Report Ref No. CC4/ASM22007518/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
2	TAILLAMPS @\$1480.00(CONSISTENT)	CRACKED	2,960.00	2,230.00
2	REAR FENDER INNER TRIMS @\$488.00(CONSISTENT)	NOT NECESSARY	976.00	-
2	FRONT SEAT BELTS @\$1100.00 (CONSISTENT)	ACTIVATED	2,200.00	1,490.00
2	FRONT SEAT BELT BUCKLES @\$650.00(CONSISTENT)	NOT NECESSARY	1,300.00	-
1	FRONT AIR BAG CONTROL UNIT (CONSISTENT)	SERVICEABLE	845.00	-
1	BATTERY CONNECTOR UNIT (CONSISTENT)	ACTIVATED	420.00	300.00
	LESS 5% DISCOUNT		-	-965.50
			31,220.90	18,344.50
	SPECIAL NETT ITEMS			
1	REAR LICENCE PLATE W/HOLDER (SN)(CONSISTENT)	BENT	50.00	40.00
1	SET REAR FLOOR PANEL INSULATOR (SN) (CONSISTENT)	NECESSARY	450.00	200.00
1	REAR END PANEL SEALANT (SN)(CONSISTENT)	NECESSARY	50.00	50.00
			550.00	290.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REAR REVERSE SENSOR .		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM .		100.00	60.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .		120.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST .		180.00	100.00
	TO RESET & DIAGNOSIS REPROGRAMME SYSTEM.		380.00	200.00
	TO DISMANTLE & REPLACED FRONT SEAT BELT.		180.00	100.00
	TO SPRAY RUST PROOFING .		150.00	80.00
	TO DISMANTLE & REFIX FUEL TANK .	NOT NECESSARY	80.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS .INCLUSIVE OF THE REPAIR OF REAR EXHAUST ASSY.		2,200.00	1,200.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,100.00
			5,320.00	2,990.00
	GRAND TOTAL		37,090.90	21,624.50



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS		17,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22007518/Upa3q2

CHUA KANG SENG

Licensed Appraiser