

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

TO AIG.

Xiao Tong

ESTIMATE OF REPAIR

Veh# : SNF4125A

Model:

BYD E6

Accident Date : 6/8/22

26/5/2022

Location : CTE TOWARDS AYE BEFORE BRADDELL EXIT ON LANE 4

3P:

SKJ4597K (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Debond.</i>	1,100.00	✓	
2	10pcs	Rear bumper clips <i>new</i>		80.00	30
3	2pcs	Rear bumper screw clips <i>new</i>		20.00	x.
4	1pc	Rear bumper lower diffuser <i>Debond</i>	340.00	✓	
5	1pc	Rear bumper enforcement <i>Dented.</i>	450.00	.355.	
6	2pcs	Rear bumper o/s & n/s reflector <i>3M</i>	225.00	x	
7	2pcs	Rear bumper o/s & n/s retainer <i>new</i>	140.00	x	
8	1pc	Rear bumper centre lamp (LED) <i>lit.</i>	310.00	185.	
9	2pcs	Rear reverse sensor <i>Dented.</i>		380.00	200.
10	1pc	Rear reverse sensor wire harness <i>new</i>	465	x.	
11	1pc	Rear reverse camera <i>new</i>		680.00	x.
12	1pc	Rear end panel <i>Dented</i>	881.90	✓	
13	2pcs	Rear end panel o/s & n/s middle retainer <i>new</i>	120.00	x.	
14	1pc	Rear end panel inner trim <i>Debond</i>	453.50	240.	
15	6pcs	Rear end panel inner trim clips <i>new</i>		48.00	20
16	1pc	Rear antenna <i>Dented</i>	320.00	158.	
17	1pc	Rear n/s tail lamp <i>new</i>	878.20	x	
18	1pc	Rear n/s tail lamp panel <i>3M</i>	353	x.	
19	1pc	Rear n/s tail lamp seal <i>new</i>	20.00	x.	
20	1pc	Rear tail gate <i>Dented.</i>	5,200.00	3850.	
21	1pc	Rear tail gate weatherstrip <i>new</i>	274.00	x.	
22	1pc	Rear tail gate emblem <i>3M</i>	101.50	✓	
23	1pc	Rear tail gate 'E6' emblem	71.00	✓	
24	1pc	Rear tail gate inner trim <i>Debond</i>	582.00	✓	
25	11pcs	Rear tail gate inner trim clips <i>new</i>		88.00	30.
26	2pcs	Rear tail gate o/s & n/s stopper <i>new</i>	40 x.		
27	1pc	Rear tail gate n/s shock absorber <i>new</i>	850.00	x.	
28	1pc	Rear tail gate centre moulding <i>new</i>	385.50	x	
29	8pcs	Rear tail gate centre moulding clips <i>new</i>		64.00	x
30	1pc	Rear tail gate lock (Upper) <i>Dented</i>	591.50	254.	
31	1pc	Rear tail gate lock (Lower) <i>new</i>	45	x.	

32	1pc	Rear tail gate n/s reflector <i>new</i>	652.50	<i>x</i>	
33	1pc	Rear windscreen sealant <i>green</i>		80.00	<i>60</i>
34	1pc	Rear windscreen moulding	140.00	<i>✓</i>	
		<i>8258.4 S.N: 340</i>	Sub Total:	14,086.60	1440.00 0.00
				10%	0% 10%
		<i>7432.56</i>	After Less %:	12,677.94	1440.00 0.00
		Labour			
1		To dismantle damaged parts, straighten & welding.	1,400.00	<i>8w</i>	
2		To spray painting.	1,000.00	<i>8w</i>	
3		To remove & refit rear windscreen.	180.00	<i>12w</i>	
4		To remove & replace rear reverse sensor camera.	50.00	<i>✓</i>	
5		To remove and replace rear tail gate (Mechanism).	100.00	<i>6w</i>	
6		To remove and replace mechanism & motor	120.00	<i>x</i>	
7		To check for fault code and resetting <i>2020</i>	500.00	<i>10w</i>	
8		To check wiring.	100.00	<i>3w</i>	
9		To re seal anti rust.	100.00	<i>6w</i>	
		Sub Total:	3,550.00		
		Total:	17,667.94		
		After Less 20%:	14,134.35		

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

total: 9792.56

h/s : 7.8K ✓

06 Days



bizSAFE
S T R

8778 1999
24 hr accident call

Mobil 1



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: