

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTIndia International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711**Our File No:** CS/III22007528/KCY3M4**Date:** 20/04/2023REFERENCE

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D20MFL0000326_02

Date of Loss: 27/07/2022

Nature of Claim: OD

Claim No: MFL2022D0004115

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMM5392M**

Make & Model: MITSUBISHI OUTLANDER, 2.0 (A)

Engine No: 4J11BC9359

Reg. Date: 03/07/2019 (Man. Year: 2019)

Chassis No: GF7W0601641

Colour: Metallic Red

Odometer: 35269 km

Engine Capacity: 1998 cc

Market Value/New Car Price: S\$134,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Toyo 7 mm

Rear Left Side: Toyo 8 mm

Front Right Side: Toyo 7 mm

Rear Right Side: Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,780.62	6,830.32	1,950.30	22.21
Miscellaneous Items	101.00	71.00	30.00	29.70
Labour	3,550.00	2,630.00	920.00	25.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,431.62	9,531.32	2,900.30	23.33
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	12,431.62	8,781.32	3,650.30	29.36
+ GST 7.00/8.00% (S\$)	870.22	702.51	167.71	19.27
Nett Amount (S\$)	13,301.84	9,483.83	3,818.01	28.70

INSPECTION

Date of Assignment: 11/08/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)

COMFORTDELGRO ENGINEERING PTE LTD

Date Inspected: 11/08/2022 Inspected At: 205 BRADDELL ROAD

SINGAPORE 579701

Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount: \$9,531.33

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2023)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM5392M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH FENDER	Bent	537.00 FL	*537.00 FL
2	1		*FRT LH FENDER WHEELARCH GARNISH	Serviceable	158.00 FL	*- FL
3	1		*FRT LH DR SIDE MIRROR ASSEMBLY	Broken	550.00 FL	*550.00 FL
4	1		*FRT LH DR SIDE MIRROR COVER	Missing	128.00 FL	*128.00 FL
5	1		*FRT LH DOOR	Bent	881.00 FL	*881.00 FL
6	1		*FRT LH DOOR GLASS	Cut	353.00 FL	*353.00 FL
7	1		*FRT LH DOOR GLASS MOULDING	Dented	149.00 FL	*149.00 FL
8	1		*FRT LH DR STICKER (BLACK)	Necessary	41.00 FL	*41.00 FL
9	1		*FRT LH DR WHEATHERSTRIP	Serviceable	168.00 FL	*- FL
10	1		*FRT LH DR HANDLE	Cracked	93.00 FL	*93.00 FL
11	1		*FRT LH DR HADBLE SEAL 1	Necessary	6.00 FL	*6.00 FL
12	1		*FRT LH DR HANDLE SEAL 2	Necessary	6.00 FL	*6.00 FL
13	1		*FRT LH DR HANDLE SWITCH	Dented	263.25 FL	*263.25 FL
14	1		*FRT LH DR HINGE TOP	Repair	42.00 FL	*- FL
15	1		*FRT LH DR HINGE LOWER	Repair	42.00 FL	*- FL
16	1		*FRT LH DR CHECKER	Serviceable	38.00 FL	*- FL
17	1		*FRT LH DOOR LOCK	Dented/Jammed	322.00 FL	*322.00 FL
18	1		*FRT LH DOOR STICKER	Not Necessary	20.00 FL	*- FL
19	1		*FRT LH DOOR OUTER MOULDING	Dented	130.00 FL	*130.00 FL
20	1		*REAR LH DOOR	Bent	851.00 FL	*851.00 FL
21	1		*REAR LH DR GLASS MOULDING	Serviceable	113.00 FL	*- FL
22	1		*REAR LH DR STICKER 1 (BLACK)	Necessary	42.00 FL	*42.00 FL
23	1		*REAR LH DR STICKER 2 (BLACK)	Necessary	72.00 FL	*72.00 FL
24	1		*REAR LH DR WHEATHERSTRIP	Cut	161.00 FL	*161.00 FL
25	1		*REAR LH DR HANDLE	Cracked	93.00 FL	*93.00 FL
26	1		*REAR LH DR HANDLE SEAL 1	Necessary	6.00 FL	*6.00 FL
27	1		*REAR LH DR HANDLE SEAL 2	Necessary	6.00 FL	*6.00 FL
28	1		*REAR LH DR HINGE TOP	Bent	42.00 FL	*42.00 FL
29	1		*REAR LH DR HINGE LOWER	Repair	42.00 FL	*- FL
30	1		*REAR LH DR CHECKER	Serviceable	37.00 FL	*- FL
31	1		*REAR LH DOOR LOCK	Repair	321.00 FL	*- FL
32	1		*REAR LH DOOR STRICKER	Not Necessary	20.00 FL	*- FL
33	1		*REAR LH DOOR OUTER MOULDING	Repeated	130.00 FL	*- FL
34	1		*REAR LH FENDER	Bent	1,298.00 FL	*1,298.00 FL
35	1		*REAR LH WHEELARCH GARNISH	Serviceable	160.00 FL	*- FL
36	1		*REAR FUEL DOOR	Serviceable	77.00 FL	*- FL
37	1		*REAR LH QUATER GLASS	Cut	713.00 FL	*713.00 FL
38	1		*REAR BUMPER	Repair	799.00 FL	*- FL
Supplementary #1						
39	1		*REAR DOOR HANDLE COVER	Missing	45.00 FL	*45.00 FL
40	1		*REAR DOOR HANDLE BASE LH	Dented	50.00 FL	*50.00 FL
41	1		*FRONT DOOR HANDLE COVER	Missing	45.00 FL	*45.00 FL
42	1		*FRONT DOOR HANDLE BASE LH	Dented	50.00 FL	*50.00 FL
43	1		*FRONT LH FENDER ARCH GARNISH LH	Cut	179.00 FL	*179.00 FL
44	1		*FRONT DOOR LOWER GARNISH LH	Necessary	171.00 FL	*171.00 FL
45	1		*REAR FENDER ARCH GARNISH LH	Cut	148.00 FL	*148.00 FL

Report was unsubmitted during this print-out.

4/20/23, 10:48 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR DOOR LOWER GARNISH LH	Necessary	158.00 FL	*158.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)					9,756.25	7,589.25
- List Item Discount on L Items 10.00/10.00% (\$)					975.63	758.93
Total Parts (\$)					8,780.62	6,830.32
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT LH FENDER INNER SHIELD CLIP (Necessary)	30.00	30.00
2	1	REAR BUMPER CLIP (Not Necessary)	30.00	0.00
3	1	REAR LH FENDER INNER SHIELD CLIP (Necessary)	30.00	30.00
4	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			101.00	71.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To knock & straighten on accident area, to remove & refit damage parts	New	1,600.00	1,200.00
2	To putty & respray on LH side affected area	New	1,400.00	1,000.00
3	To check wiring	New	50.00	30.00
4	To remove & refit FRT LH Door trim, door glass, window regulator, door lock to assist work load	New	100.00	80.00
5	To remove & refit REAR LH Door trim, door glass, window regulator, door lock to assist work load	New	100.00	80.00
6	To remove & refit REAR LH quarter glass.	New	100.00	60.00
7	To remove & refit inner seat & upholstery to assist work load	New	100.00	100.00
8	To remove & refit petrol tank to assist work load.	New	100.00	80.00
Gross Labour Cost (\$\$)			3,550.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >