

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC22007530/Kcy3e2	
	300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date:	23/08/2022	
				Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	XD 9058U	Veh. Inspected	l	SGJ 132S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/22/VC05/026119	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		08/08/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	AUDI RS7 (A)	c.c		3996	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	WUAZZZF27MN902831	Colour		METALLIC GREY	
	Odometer	10948 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	285/30Z R22	PIRELLI		7 mm	
	L/H Front Tyre	285/30Z R22	PIRELLI		7 mm	
	R/H Rear Tyre	285/30Z R22	PIRELLI		7 mm	
	L/H Rear Tyre	285/30Z R22	PIRELLI		7 mm	
4.	Description of Damages					
	THE VEHICLE SUS	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S DOOR.				
5.	General Information					
	Accident Date	04/08/2022	Inspect Date /	Time	12/08/2022 (11:08 AM)	
	Survey held at	THIAM HENG HUAT PTE LTD				
		176 SIN MING DRIVE #05-14 SINGAPORE 575721				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22007530/Kcy3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

1

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser