

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22007537/GVCM4**Date:** 06/02/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001880702
Claimant Vehicle No :	SMN1720X	Insured Vehicle No :	FBR9185Y
Date of Loss:	05/08/2022	Nature of Claim:	TP
		Claim No:	281468

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN1720X	Engine No:	A25A0205051
Make & Model:	TOYOTA CAMRY, 2.5 G HYBRID CVT (A)	Chassis No:	AXVH701031293
Reg. Date:	26/07/2019 (Man. Year: 2018)	Odometer:	74849 km
Colour:	Silver		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,635.67	1,401.52	234.15	14.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	900.00	160.00	15.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,695.67	2,301.52	394.15	14.62
+ GST 8.00/8.00% (S\$)	215.65	184.12	31.53	14.62
Nett Amount (S\$)	2,911.32	2,485.64	425.68	14.62

INSPECTION

Date of Assignment:	10/08/2022	
Date Inspected:	23/08/2022	Inspected At: Vin's Motor Pte Ltd 160 Sin Ming Drive, #03-03 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Feb 2023)
Parts:	143	TOYOTA CAMRY 2.5 G HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN1720X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR OUTER HANDLE	Cut	469.10 FL	*381.50 FL
2	1		*REAR LH DOOR	Dented	1,487.20 FL	*1,487.20 FL
3	1		*REAR LH DOOR OUTER MOULDING	Not Necessary	120.40 FL	*- FL
4	1		*REAR LH DOOR PILLAR GARNISH	Not Necessary	104.20 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					2,180.90	1,868.70
- List Item Discount on L Items 25.00/25.00% (\$\$)					545.23	467.18
Total Parts (\$\$)					1,635.67	1,401.52

F=Franchise part, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR DAMAGES	New	380.00	300.00
2	TO SPRAY PAINTING	New	680.00	600.00
Gross Labour Cost (S\$)			1,060.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >