

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI22005303/RNY3E2-1

Date: 17/08/2022

REFERENCE

| | | | | | |
|------------------------------|---|-----------------------------|--------------------|-----------|-------------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMPCSNW00064512101 | | |
| Claimant Vehicle No : | SLH3311Z | Insured Vehicle No : | SMF3389Z | | |
| Date of Loss: | 15/02/2022 | Nature of Claim: | TP | Claim No: | SNM22D201179/C02/CHNGPW |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No: | SLH3311Z | Engine No: | 3ZRB837006 |
| Make & Model: | TOYOTA HARRIER, 2.0 Elegance (A) | Chassis No: | ZSU600084355 |
| Reg. Date: | 07/10/2016 (Man. Year: 2016) | Odometer: | 54915 km |
| Colour: | Black | | |
| Engine Capacity: | 1986 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|--|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes | |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 225/65 R17 | Rear Tyre Size: | 225/65 R17 |
| Front Left Side: | Yokohama 6 mm | Rear Left Side: | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-----------------|-----------------|-----------------|--------------|
| Parts | 3,801.00 | 1,120.25 | 2,680.75 | 70.53 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,960.00 | 960.00 | 1,000.00 | 51.02 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 5,761.00 | 2,080.25 | 3,680.75 | 63.89 |
| Approved Total (Overridden) (\$\$) | | 1,650.00 | | |
| Nett Amount (\$\$) | 5,761.00 | 1,650.00 | 4,111.00 | 71.36 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 03/06/2022 | HUP LEY HUAT MOTOR SPRAY PAINTING SVS (HQ) |
| Date Inspected: | 13/06/2022 Inspected At: | BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY Singapore 417883 |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: MOHD RASUL

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|---|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 17 Aug 2022) |
| Parts: | M1-SUV | TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLH3311Z) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--|-----|----------|---------------------------|---------------|------------|------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 1,220.00 F | *866.00 FL |
| 2 | 1 | | *REAR BUMPER LOWER | Scratched | 321.00 F | *321.00 FL |
| 3 | 1 | | *RH SIDE RETAINER | Not Necessary | 55.00 F | *- FL |
| 4 | 1 | | *RH REAR BUMPER REFLECTOR | Not Necessary | 65.00 F | *- FL |
| 5 | 1 | | *REAR BOOT COVER | Repair | 1,680.00 F | *- FL |
| 6 | 1 | | *REAR BUMPER CLIP | Necessary | 50.00 FS | *30.00 FS |
| 7 | 1 | | *REAR BUMPER SENSOR | Not Working | 360.00 FS | *200.00 FS |
| 8 | 1 | | *SET CARPLATE | Not Necessary | 50.00 FS | *- FS |
| F=Franchise part. S=SpcNett. L=ListItemDisc. | | | | | | |
| Sub Total (\$\$) | | | | | 3,801.00 | 1,417.00 |
| - List Item Discount on L Items 0.00/25.00% (\$\$) | | | | | 0.00 | 296.75 |
| Total Parts (\$\$) | | | | | 3,801.00 | 1,120.25 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO TUFF COAT AFFECTED AREAS | New | 120.00 | 0.00 |
| 2 | TO SPRAY PAINT INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIR BODY PORTIONS WHERE CONSISTENT TO THE ACCIDENT | New | 800.00 | 600.00 |
| 3 | TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO REALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT | New | 800.00 | 300.00 |
| 4 | TO REMOVE, REFIT, REPLACE DAMAGED SENSOR AND CHECK UP ELECTRICAL WIRING | New | 120.00 | 60.00 |
| 5 | LABOR TO REMOVE AND REFIT WINDSCREEN | New | 120.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 1,960.00 | 960.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >