

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22007540/APA3Q2**Date:** 28/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000102
Claimant Vehicle No :	SJM6124A	Insured Vehicle No :	SMT9564X
Date of Loss:	02/08/2022	Nature of Claim:	TP
		Claim No:	4247795576SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM6124A	Engine No:	L15A5205556
Make & Model:	HONDA AIRWAVE, 1.5 M (A)	Chassis No:	GJ11304614
Reg. Date:	12/01/2009 (Man. Year: 2008)	Odometer:	138608 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,366.72	10,682.96	9,683.76	47.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,790.00	3,700.00	3,090.00	45.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,156.72	14,382.96	12,773.76	47.04
Approved Total (Overridden) (S\$)		11,500.00		
Nett Amount (S\$)	27,156.72	11,500.00	15,656.72	57.65
+ Loss of Use (13.0 x S\$60.00/day) (S\$)		780.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,287.45		
Global Sum Settlement (S\$)		12,200.00		

INSPECTION

Date of Assignment:	04/08/2022	HD Perfect Autowork Pte Ltd (HQ)
Date Inspected:	04/08/2022 Inspected At:	8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Estimated Period of Repair:	12.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	1,482.50 FL	*1,185.00 FL
2	2		*TAILGATE HINGE	Bent	276.40 FL	*276.40 FL
3	2		*TAILGATE LAMP	Cracked	590.40 FL	*590.40 FL
4	2		*TAILGATE DAMPER	Not Necessary	250.00 FL	*- FL
5	1		*TAILGATE LOGO	Necessary	45.20 FL	*45.20 FL
6	1		*TAILGATE EMBLEM AIRWAVE	Necessary	59.00 FL	*59.00 FL
7	1		*TAILGATE OUTER GARNISH	Deformed	456.00 FL	*456.00 FL
8	1		*TAILGATE OUTER MOULDING	Not Necessary	478.00 FL	*- FL
9	1		*TAILGATE OUTER HANDLE	Not Necessary	160.00 FL	*- FL
10	1		*TAILGATE INNER TRIM	Cracked	296.00 FL	*296.00 FL
11	1		*TAILGATE INNER LOCK	Damaged	246.00 FL	*246.00 FL
12	1		*TAILGATE WEATHERSTRIP	Cut	194.00 FL	*194.00 FL
13	2		*TAILGATE STOPPER	Not Necessary	38.00 FL	*- FL
14	1		*TAILGATE INNER HOLDER	Missing	58.00 FL	*58.00 FL
15	1		*TAILGATE THIRD BRAKE LIGHT WITH BASE	Not Necessary	215.80 FL	*- FL
16	1		*TAILGATE WINDSCREEN MOULDING	Necessary	169.00 FL	*169.00 FL
17	2		*REAR NUMBER PLATE LAMP	Not Necessary	108.00 FL	*- FL
18	1		*REAR BUMPER	Distorted	1,078.50 FL	*1,078.50 FL
19	1		*REAR BUMPER BEAM	Bent	197.00 FL	*197.00 FL
20	2		*REAR BUMPER SIDE RETAINER	Necessary	90.00 FL	*90.00 FL
21	2		*TAILLAMP	Cracked	717.00 FL	*717.00 FL
22	2		*TAILLAMP PANEL (INNER)	Not Necessary	850.00 FL	*- FL
23	2		*TAILLAMP PANEL (OUTER)	Dented	794.00 FL	*794.00 FL
24	1		*REAR FENDER	O/S Buckled	3,308.00 FL	*998.00 FL
25	2		*REAR FENDER INNER COWLING	Not Necessary	339.00 FL	*- FL
26	2		*REAR FENDER INNER TRIM (LOWER)	Deformed	1,396.00 FL	*793.00 FL
27	2		*REAR FENDER INNER TRIM (UPPER)	Not Necessary	997.80 FL	*- FL
28	2		*REAR FENDER GLASS WITH MOULDING	Not Necessary	1,590.00 FL	*- FL
29	1		*REAR TOWING HOOK PANEL	Repair	223.60 FL	*- FL
30	1		*REAR END PANEL	Distorted	509.70 FL	*509.70 FL
31	1		*REAR END PANEL TOP GARNISH	Deformed	189.50 FL	*189.50 FL
32	1		*REAR END PANEL BOTTOM (CENTRE)	Distorted	358.00 FL	*358.00 FL
33	2		*REAR END PANEL BOTTOM EXTENSION	Distorted	396.00 FL	*396.00 FL
34	1		*REAR SPARE TYRE BOLT	Bent	45.00 FL	*45.00 FL
35	1		*REAR CHASSIS MEMBER RH	Repair	980.00 FL	*- FL
36	1		*REAR FLOOR PANEL	Distorted	1,396.50 FL	*1,195.00 FL
37	1		*REAR FLOOR PANEL TOP BOARD	Deformed	548.70 FL	*548.70 FL
38	1		*TOOLS TRAY	Torn	194.30 FL	*194.30 FL
39	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
40	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
41	1		*SET TAILGATE OUTER GARNISH CLIP	Necessary	30.00 FS	*20.00 FS
42	1		*SET TAILGATE OUTER MOULDING CLIP	Not Necessary	30.00 FS	*- FS
43	1		*SET TAILGATE INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
44	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
45	1		*TAILGATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*30.00 FS
46	1		*SET TAILLAMP CLIP	Necessary	30.00 FS	*20.00 FS
47	1		*TAILLAMP PANEL (INNER) SEALANT RH	Not Necessary	60.00 FS	*- FS
48	1		*TAILLAMP PANEL (OUTER) SEALANT RH	Necessary	60.00 FS	*40.00 FS
49	2		*REAR FENDER SEALANT	Necessary	160.00 FS	*40.00 FS
50	1		*SET REAR FENDER INNER COWLING	Not Necessary	50.00 FS	*- FS
51	1		*REAR FENDER INNER TRIM (LOWER) CLIP RH	Necessary	50.00 FS	*50.00 FS
52	1		*REAR FENDER INNER TRIM(UPPER)CLIP RH	Not Necessary	50.00 FS	*- FS
53	2		*REAR FENDER QUARTER GLASS SEALANT	Necessary	120.00 FS	*40.00 FS
54	2		*REAR FENDER QUARTER GLASS INNER SEAL	Not Necessary	80.00 FS	*- FS
55	2		*REAR FENDER QUARTER GLASS SOLAR FILM	Not Necessary	500.00 FS	*- FS

Report was unsubmitted during this print-out.

4/28/23, 3:43 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET REAR DOOR INNER TRIM CLIP RH	Not Necessary	50.00 FS	*- FS
57	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
58	1		*REAR END PANEL BOTTOM (CENTRE) SEALANT	Necessary	120.00 FS	*40.00 FS
59	1		*REAR FLOOR PANEL INSULATOR SEAL	Necessary	350.00 FS	*200.00 FS
60	1		*TRAINGLE BREAK DOWN SIGN	Damaged	180.00 FS	*120.00 FS
61	1		*REVERSE CAMERA	Damaged	550.00 FS	*380.00 FS
62	1		*REVERSE SENSOR	Damaged	320.00 FS	*200.00 FS
63	1		*JACK	Not Necessary	180.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					24,630.90	13,018.70
- List Item Discount on L Items 20.00/20.00% (S\$)					4,264.18	2,335.74
Total Parts (S\$)					20,366.72	10,682.96
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	2,600.00	1,600.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,400.00
3	TUFF COAT	New	250.00	120.00
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	200.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REAR CHASSIS ALIGNMENT	New	250.00	0.00
8	TRANFER TAILGATE MECHANISM	New	80.00	80.00
9	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
11	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
12	REMOVE AND REFIX PETROL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	New	100.00	0.00
13	REMOVE AND REFIX REAR SPOILER	New	80.00	0.00
14	REMOVE AND REFIX VIDEO CAMERA	New	120.00	50.00
15	REMOVE AND REFIX REAR FENDER GLASS RH	New	200.00	0.00
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			6,790.00	3,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >