



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 2618Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	RH/F DISC WHEEL (SN)	CUT	1,375.22	1,375.18
1	RH/F FENDER (SN)	BUCKLED	1,123.11	1,123.11
1	RH/F FENDER EMBLEM (SN)	NECESSARY	117.24	117.24
1	FRT BUMPER (SN)	CUT	1,753.22	1,753.22
1	RH/F BUMPER BRACKET (SN)	NOT NECESSARY	18.53	-
1	RH/F OUTER PARKING SENSOR (SN)	NOT NECESSARY	195.43	-
1	RH/F PARKING SENSOR SEAL (SN)	NOT NECESSARY	7.10	-
1	RH/F BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	112.27	-
			4,702.12	4,368.75
	<b><u>LABOUR</u></b>			
	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	SUPPLY & TRANSFER 1PC FRONT RIGHT RIM.		60.00	60.00
	INSPECT & CONDUCT WHEEL ALIGNMENT.		540.00	540.00
	REMOVE & REPLACE FRONT BUMPER, FRONT RIGHT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.		1,920.00	1,440.00
	RESPRAY FRONT BUMPER & FRONT RIGHT FENDER.		1,800.00	1,600.00
			4,700.00	4,020.00
<b>GRAND TOTAL</b>			<b>9,402.12</b>	<b>8,388.75</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>8,388.75</b>

Report Ref No. CS/FCI22007542/Gvce2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.