



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI22007542/Gvce2 Date: 08/11/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBS 6555C	Veh. Inspected	SKE 2618Z
Policy No.		Coverage (\$)	0.00
Claim No.	D22002435MFBP	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	08/08/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E250	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2120362B303427	Colour	BLUE
Odometer	133187 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R18	GOODYEAR	6 mm
L/H Front Tyre	245/40 R18	GOODYEAR	6 mm
R/H Rear Tyre	245/40 R18	GOODYEAR	6 mm
L/H Rear Tyre	245/40 R18	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/08/2022	Inspection Date	08/08/2022
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	