

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22007543/RVCQ2**Date:** 21/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW000242912100

**Claimant Vehicle No :** PC7669U **Insured Vehicle No :** SMQ4996G

Date of Loss: 03/08/2022 Nature of Claim: TP Claim No: SNM22D205462/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **PC7669U**

Make & Model: YUTONG ZK6119H, 3.0 D (A) Engine No: ISB67E6C29022315090

Reg. Date: 20/09/2018 (Man. Year: 2018) Chassis No: LZYTBTE61J1020635

Colour: Grey Odometer: 219919 km

Engine Capacity: 6690 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Continental 8 mm Rear Left Side: Continental 8/8 mm

Front Right Side: Continental 8 mm Rear Right Side: Continental 8/8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,749.10	2,730.00	3,019.10	52.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,950.00	3,060.00	4,890.00	61.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,699.10</b>	<b>5,790.00</b>	<b>7,909.10</b>	<b>57.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,600.00</b>		
<b>(S\$)</b>	13,699.10	4,600.00	9,099.10	66.42
<b>+ GST 7.00/7.00% (S\$)</b>	958.94	322.00	636.94	66.42
<b>Nett Amount (S\$)</b>	<b>14,658.04</b>	<b>4,922.00</b>	<b>9,736.04</b>	<b>66.42</b>

**INSPECTION**

Date of Assignment: 19/10/2022

Date Inspected: 11/10/2022 Inspected At: SC Auto Industries (S) Pte Ltd (HQ)  
51 Senoko Road, #03-01  
Singapore 758133

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 21 Dec 2022)	
<b>Parts:</b>	N/A	YUTONG ZK6119H 3.0 D (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC7669U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	1,850.00 F	*1,850.00 F
2	1		*REAR REVERSE SENSOR (4 PCS)	Not Working (2 PCS ONLY)	537.00 F	*268.50 F
3	8		*REAR NUMBER PLATE WITH HOLDER	Cracked (1 PCS ONLY)	80.00 F	*40.00 F
4	1		*REAR PANEL INNER	Repair	1,980.00 F	*- F
5	1		*INFORMATION STICKER	Necessary	80.00 F	*15.00 F
6	1		*REAR NUMBER PLATE LIGHT	Cracked	385.60 F	*320.00 F
7	1		*REAR EMBLEM	Necessary	186.50 F	*186.50 F
8	1		*ARTWORK	Not Necessary	450.00 F	*- F
9	1		*SUNDRIES	Necessary	200.00 F	*50.00 F
F=Franchise part.						
<b>Total Parts (S\$)</b>					<b>5,749.10</b>	<b>2,730.00</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE ,REINSTALL AND CHECK	New	800.00	100.00
2	LABOUR TO REMOVE ,REPAIR AND REINSTALL REAR BUMPER ,REAR PANEL ,TAILGATE	New	4,000.00	1,600.00
3	LABOUR TO RESPRAY REAR BUMPER ,REAR PANEL,TAILGATE	New	2,800.00	1,280.00
4	LABOUR TO CARRY OUT DIAGNOSTIC CHECK	New	350.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,950.00</b>	<b>3,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >