



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22003666/Rcy3e2-1	
			Date: 24/08/2022	
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBG 8308A	Veh. Inspected	GBH 4132K
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/22/22/VC05/025696	Excess (\$)	0.00
	Assign From	ONG LI LI	Assign Date	08/08/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA HIACE VAN TURBO 5DR	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JTFHT02P600242416	Colour	GREY
	Odometer	109457 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	MICHELIN	6 mm
	L/H Front Tyre	195 R15C	MICHELIN	6 mm
	R/H Rear Tyre	195 R15C	MICHELIN	6 mm
	L/H Rear Tyre	195 R15C	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	18/04/2022	Inspection Date	26/04/2022
	Survey held at	HIAP LEK AUTOMOBILE TRADING 160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	