



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5509G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	PANEL SUB-ASSY, FRONT DOOR, RH	BENT	1,300.70	1,300.70
1	LOCK ASSY, FRONT DOOR W/MOTOR, RH	TO REPAIR SEE LABOUR	603.20	-
1	MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH	SERVICEABLE	38.60	-
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	SERVICEABLE	193.50	-
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	SERVICEABLE	390.60	-
1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	SERVICEABLE	926.00	-
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	SERVICEABLE	321.10	-
1	HINGE ASSY, FRONT DOOR, LOWER RH	TO REPAIR SEE LABOUR	110.60	-
1	HINGE ASSY, FRONT DOOR, UPPER RH	TO REPAIR SEE LABOUR	97.50	-
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	TO REPAIR SEE LABOUR	238.30	-
1	TAPE, BLACK OUT, NO.2 FRT RH	NECESSARY	43.50	43.50
1	TAPE, BLACK OUT, NO.1 FRT RH	NECESSARY	13.30	13.30
1	TAPE, BLACK OUT, NO.3 FRT RH	NECESSARY	26.30	26.30
	LESS 25% DISCOUNT		-1,075.80	-345.95
			3,227.40	1,037.85
<u>SPECIAL NETT ITEMS</u>				
1	DOOR STICKER TRANSCAB (SN)	NECESSARY	100.00	60.00
2	DOOR TRIM CLIP (SN)	NOT NECESSARY	150.00	-
2	DOOR WEATHERSTRIP CLIP (SN)	NOT NECESSARY	160.00	-
			410.00	60.00
<u>LABOUR</u>				
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		240.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF LOCK ASSY, FRONT DOOR W/MOTOR, RH, HINGE ASSY, FRONT DOOR, LOWER RH, HINGE ASSY, FRONT DOOR, UPPER RH AND REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH.		1,600.00	200.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	220.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIT OF FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			4,930.00	465.00
	GRAND TOTAL		8,567.40	1,562.85
RECOMMENDED COST OF REPAIRS				1,562.85

Report Ref No. CS/GAI22007547/Kvce2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.