



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 362P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	1,933.20	-
1	WHEELARCH REAR RH	SERVICEABLE	275.40	-
1	BONNET	TO REPAIR SEE LABOUR	1,312.70	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	237.40	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	237.40	-
1	HEADLAMP RH	SERVICEABLE	743.60	-
1	ROCKER PANEL OUTER RH	SERVICEABLE	1,184.99	-
1	DOOR MIRROR RH	SERVICEABLE	1,483.40	-
1	FENDER PANEL FRT RH	BENT	437.10	437.10
1	WHEELARCH FRT RH	SERVICEABLE	191.40	-
1	BUMPER COVER FRT	SERVICEABLE	747.20	-
1	BUMPER BRACKET KIT FRT RH	SERVICEABLE	101.40	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-1,172.99	-43.71
			10,556.86	393.39
<u>SPECIAL NETT ITEMS</u>				
1	FENDER CLIP (SN)	NOT NECESSARY	120.00	-
1	FENDER LINER CLIP (SN)	NOT NECESSARY	130.00	-
1	FRT BUMPER CLIP (SN)	NOT NECESSARY	65.00	-
1	RIM (SN)	SERVICEABLE	350.00	-
1	DOOR STICKER TRANSCAB (SN)	NOT NECESSARY	100.00	-
1	DOOR ADVERTISEMENT (SN)	NOT NECESSARY	200.00	-
2	WINDSCREEN SEALANT (SN)	NOT NECESSARY	150.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	200.00	-
1	WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	130.00	-
			1,445.00	-

Report Ref No. CS/AGI22007548/Kce2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FENDER PANEL REAR RH, BONNET, BONNET HINGE LH, BONNET HINGE RH AND DOOR PANEL FRT RH.		6,000.00	300.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
			10,240.00	770.00
	GRAND TOTAL		22,241.86	1,163.39
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			950.00

Report Ref No. CS/AGI22007548/Kce2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.